

Ford
THE UNIVERSAL CAR

Price List of
Miscellaneous
Parts

5

Model T

Ford Motor Company
DETROIT, MICH.

PRICE LIST OF MISCELLANEOUS PARTS


Ford Model T

Effective December 15th, 1920

NOTE—Garages will receive the regular garage discount on all parts listed in this catalog, except on those parts on which a "Dealer's Net Price" is given. On such parts Garages will receive a discount of 10% from list.


Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
COUPELET—1915-20 WINDSHIELD						
1	9541	W. S. complete	1916-19	\$31 00		BO
2	9542	W. S. assem., upper	1916-19	12 50		BO
2B	9524B	W. S. assembly—upper—Cp. Sn.	1920	12 50		BO
3	9543	W. S. assem., lower	1916-19	12 50		BO
4	9025	Bolt and nut (glass clip)—Cp. Tn. Sn.	1915-20	10		BO
4B	8689	Bracket (hinge pillar)—Cp. Sn.	1920	1 00		BO
5	9530	Bracket (up. hinge pillar) R.—Cp. Sn.	1915-19	1 00		BO
6	9531	Bracket (up. hinge pillar) L.—Cp. Sn.	1915-19	1 00		BO
7	9532	Bracket (up. hinge sash) R.—Cp. Sn.	1916-19	1 00		BO
8	9004	Bracket (vent. hinge body) R.	1915-19	1 00		BO
9	9533	Bracket (up. hinge sash) L.—Cp. Sn.	1916-19	1 00		BO
10	9005	Bracket (vent. hinge body) L.	1915-19	1 00		BO
11	9002	Bracket (vent. hinge sash) R.—Cp. Tn. Sn.	1915-20	20		BO
12	9003	Bracket (vent. hinge sash) L.—Cp. Tn. Sn.	1915-20	20		BO
13	9066	Channel (center) rubber—Cp. Tn. Sn.	1915-20	40		BO
14	9013	Clip (lower glass) Cp. Tn. Sn.	1915-20	10		BO
15	9011	Clip (upper glass) R.—Cp. Sn.	1915-20	10		BO
16	9012	Clip (upper glass) L.—Cp. Sn.	1915-20	10		BO
17	9021	Cone (up. hinge friction) Cp. Sn.	1915-19	15		BO
18	9550	Glass 37 $\frac{1}{8}$ x 9 $\frac{7}{8}$ "	1916-19	8 50		NT
19	9528	Hinge assem., up. R.—Cp. Sn.	1916-19	2 00		BO
19B	9528B	Hinge assem., up. R.—Cp. Sn.	1920	2 25		BO
20	9529	Hinge assem., up. L.—Cp. Sn.	1916-19	2 00		BO
20B	9529B	Hinge assem., up. L.—Cp. Sn.	1920	2 25		BO
21	9000	Hinge assem., vent. R.	1915-19	1 00		BO
22	9001	Hinge assem., vent. L.	1915-19	1 00		BO
23	9014	Handle (lower sash) Cp. Tn. Sn.	1915-20	20		BO
24	9026	Nut (glass clip) Cp. Tn. Sn.	1915-20	05		BO
25	9027	Retainer (glass) side	1915-19	20		BO
25B	9090	Retainer (glass)—Sn. 1915-20	1920	95		BO
26	9028	Retainer (glass) up. and lower	1915-19	55		BO
27	9572	Retainer (weather strip) upper	1916-19	20		BO
28	9573	Retainer (weather strip) side	1916-19	15		BO
29	9544	Sash, upper	1916-19	7 50		BO
30	9545	Sash, lower	1916-19	7 50		BO
31	9575	Strip (up. weather) rubber	1916-19	50		BO
32	9576	Strip (side weather) rubber	1916-19	15		BO
33	9574	Screw (up. hinge clamp) Cp. Tn. Sn.	1916-19	35		BO

Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.




Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
COUPELET—1915-20 WINDSHIELD—Continued						
33B	9574B	Screw (upper hinge clamp)—Cp. Sn.	1920	\$ 0 50		BO
34	9006	Screw (vent. thumb) (specify black or nickel) Cp. Tn. Sn.	1916-20	25		BO
35	9022	Screw (up. hinge friction cone) Cp. Sn.	1915-19	05		BO
36	9023	Washer (up. hinge friction lock) Cp. Sn.	1915-19	01		NT
SEDAN—1915-20 WINDSHIELD						
37	9538	W. S. complete	1916-20	31 00		BO
38	9524	W. S. assem.—upper	1916-20	12 50		BO
39	9525	W. S. assem.—lower	1916-20	12 50		BO
40	9530	Bracket (up. hinge pillar) R. (Order No. 5)				
41	9531	Bracket (up. hinge pillar) L. (Order No. 6)				
42	9046	Bracket (vent. hinge pillar) R.	1915-20	40		BO
43	9047	Bracket (vent. hinge pillar) L.	1915-20	40		BO
44	9534	Glass 37 $\frac{1}{2}$ x 9 $\frac{3}{4}$ "	1916-20	8 50		NT
45	9042	Hinge assem.—vent. R.	1915-20	1 00		BO
46	9043	Hinge assem.—vent. L.	1915-20	1 00		BO
49	9536	Retainer (weather strip) up.	1916-20	20		
50	9537	Retainer (weather strip) side	1916-20	15		
51	9526	Sash—upper	1916-20	7 50		BO
52	9527	Sash—lower	1916-20	7 50		BO
53	9645	Strip (weather) side rubber	1916-20	25		BO
54	9646	Strip (weather) up. rubber	1916-20	50		BO


Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.



37



51



45

47



48



52

Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
TOURING AND TORPEDO BODY						
57	8198	Anti-rattler (rear seat panel)	1916-20	\$ 0 35		BO
57B	7107	Anti-rattler (deck front) Torp.	1920	15		BO
57C	7108	Anti-rattler (deck rear) Torp.	1919-20	15		BO
58	8470	Bar (rear seat) metal	1915-17 and 20	1 00		BO
59	5171	Bar (rear seat) wood	1918-19	60		BO
59B	7243	Bar assembly (rear seat frame) T. C.	1920	75		BO
60	7146	Board (rear floor)	1915-19	60		BO
61	5144	Board (front heel)	1915-20	1 75		BO
61B	5187	Board (rear heel) T. C.	1915-20	2 00		
62	8349	Board assem. (rear heel)	1916-20	1 60		BO
62B	6606	Board assembly (instrument)	1919-20	2 00		
63	5197	Board assem. (tool box bottom)	1915-19	1 35		BO
64	7148	Board (rear seat toe) steel	1915-17 and 20	1 50		BO
65	5162	Board (rear seat toe) wood	1918-19	1 35		BO
66	7266	Bottom (front seat)	1915-20	1 25		BO
67	8372	Bottom assem. (front seat) steel	1915-17 and 20	1 80		BO
68	5131	Bottom assem. (front seat) wood	1918-19	1 50		BO
69	7143	Box (under rear seat tool) steel	1915-17 and 20	1 50		BO
70	5266	Box (under rear seat tool) wood	1918-19	1 00		BO
71	8191	Brace (front seat)	1916-20	05		
72	5175	Brace (rear seat frame riser)	1918-19	15		BO
73	8003	Bracket (cowl to body) R.	1915-17	15		BO
74	8135	Bracket (cowl to body) L.	1915-17	15		BO
75	8469	Bracket (cowl to body) R.	1918-20	15		BO
76	8470	Bracket (cowl to body) L.	1918-20	20		BO
77	8474	Bracket (dash pillar) R.	1917-20	30		BO
78	8475	Bracket (dash pillar) L.	1917-20	30		BO
79	7144	Bracket (rear trim rail to pillar) R.	1915-20	30		BO
80	7145	Bracket (rear trim rail to pillar) L.	1915-20	30		BO
81	8350	Cowl assem.	1915-20	4 50		BO
82	7023	Deck assem. (rear) finished	1914-20	13 00		BO
83	7023	Deck assem. (rear) prime	1914-20	9 00		BO
84	5116	Door assem. (front) R.	1915-20	6 00		BO
85	7118	Door assem. (rear) R.	1915-20	6 00		BO
86	7119	Door assem. (rear) L.	1915-20	6 00		BO
87	8021	Door assem. (deck)	1913-20	2 50		BO
87B	5308	Door (battery trap) Torp.	1920	1 00		BO
88	5569	Fastener assem. (deck door)	1913-20	30		BO
89	7150	Frame (front seat side) T. C.	1915-20	60		BO
90	7149	Frame (front seat rear) T. C.	1915-20	60		BO
91	8429	Frame (seat side) R., Torp.	1917-20	35		BO
92	8430	Frame (seat side) L., Torp.	1917-20	35		BO
93	8442	Frame (seat rear) Torp.	1917-20	1 00		BO
94	8347	Frame assem. (rear seat) R., steel	1916-17 and 20	1 20		BO

Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
TOURING AND TORPEDO BODY—Continued						
95	8348	Frame assem. (rear seat) L., steel	1916-17 and 20	\$1 20	BO	
96	8332	Frame assem. (front seat side) R.	1918-19	50	BO	
97	8333	Frame assem. (front seat side) L.	1918-19	50	BO	
98	5218	Frame assem. (rear seat) wood	1918-19	1 80	BO	
99	5297	Hinge assem. (door)	1914-20	50		
100	8002	Hinge (seat bottom)	1915-20	05	BO	
101	5151	Hinge (seat bottom) T. C.	1918-19	05	BO	
102	5568	Hinge (deck door)	1913-20	10	BO	
103	5189A	Iron (rear seat corner top) L.	1915-17 and 20	60	BO	
104	5189B	Iron (rear seat corner top) L.	1918-19	60	BO	
105	5190A	Iron (rear seat corner top) R.	1915-17 and 20	60	BO	
106	5190B	Iron (rear seat corner top) R.	1918-19	60	BO	
107	5178	Iron (rear seat side top) L.	1915-20	55	BO	
108	5179	Iron (rear seat side top) R.	1915-20	55	BO	
109	5145	Iron (front seat top) T. C.	1915-20	55	BO	
110	5389	Iron (short top) Torp.	1913-16	50	BO	
111	8401	Iron (short top) Torp.	1917-20	60	BO	
112	5392	Iron (long top) R., Torp.	1913-16	60	BO	
113	8431	Iron (long top) R., Torp.	1917-20	60	BO	
114	5391	Iron (long top) L., Torp.	1913-16	60	BO	
115	8432	Iron (long top) L., Torp.	1917-20	60	BO	
116	5679	Lock (rear door) R.	1913-20	50	BO	
117	5680	Lock (rear door) L. and Front R.	1913-20	50	BO	
118	7128	Panel (front door) R.	1915-20	1 50	BO	
119	7129	Panel (rear door) R.	1915-20	1 75	BO	
120	7121	Panel (rear door) L.	1915-20	1 75	BO	
121	5123	Panel (front side) R., T. C.	1915-20	6 00	BO	
122	5122	Panel (front side) L., T. C.	1915-20	6 00	BO	
123	7159	Panel (rear side) R., T. C.	1915-20	2 00	BO	
124	7160	Panel (rear side) L., T. C.	1915-20	2 00	BO	
125	7147	Panel (front seat back) T. C.	1915-20	5 00	BO	
126	7218	Panel (rear seat back)	1915-20	2 75	BO	
127	7157	Panel (rear seat corner) R.	1915-20	2 00	BO	
128	7158	Panel (rear seat corner) L.	1915-20	2 00	BO	
129	8449	Panel and rail assem. (front back) T. C.	1915-20	3 50	BO	
130	8450	Panel and rail assem. (rear back)	1915-20	10 50		
131	8453	Panel and seat assem. (rear back)	1917-20	17 00	BO	
132	8156	Panel and frame assem.—R., T. C.	1915-20	12 00	BO	
133	8157	Panel and frame assem.—L., T. C.	1915-20	12 00	BO	
134	8420	Panel and frame assem. (side) R., Torp.	1915-20	12 00	BO	
135	8421	Panel and frame assem. (side) L., Torp.	1915-20	12 00	BO	
136	8132	Panel (front side) R., Torp.	1915-20	3 25	BO	
137	8133	Panel (front side) L., Torp.	1915-20	3 25	BO	
138	6638	Panel (seat side) R., Torp.	1914-20	3 25	BO	
139	6639	Panel (seat side) L., Torp.	1914-20	3 25	BO	


Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.


Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
TOURING AND TORPEDO BODY—Continued						
140	6642	Panel (deck side) R.	1914-20	\$ 1 00	BO	
141	6641	Panel (deck side) L.	1914-20	1 00	BO	
142	6640	Panel assem. (back and deck)	1914-20	6 00	BO	
143	7193	Pillar (dash) R.	1915-20	30	BO	
144	7194	Pillar (dash) L.	1915-20	30	BO	
145	7195	Pillar (panel) R.	1915-20	35	BO	
146	7196	Pillar (panel) L.	1915-20	35	BO	
147	7197	Pillar (front seat front) R.	1915-20	35	BO	
148	7198	Pillar (front seat front) L.	1915-20	35	BO	
149	7200	Pillar (front seat rear) R., T. C.	1915-20	35	BO	
150	7201	Pillar (front seat rear) L., T. C.	1915-20	35	BO	
151	7202	Pillar (rear seat) R.	1915-20	60	BO	
152	7203	Pillar (rear seat) L.	1915-20	60	BO	
153	7270	Post (front door front)	1915-20	30	BO	
154	7271	Post (front door rear)	1915-20	30	BO	
155	7278	Post (rear door front) R.	1915-20	30	BO	
156	7279	Post (rear door front) L.	1915-20	30	BO	
157	7280	Post (rear door rear) R.	1915-20	30	BO	
158	7281	Post (rear door rear) L.	1915-20	30	BO	
159	7015	Plate (rear lock striker) R.	1914-16	05	BO	
160	7017	Plate (rear lock striker) L. and Frt. R.	1914-16	05	BO	
161	8433	Plate (lock striker)	1917-20	15	BO	
162	5205	Pin (door hinge)	1912-20	01	NT	
163	7216	Rail (front seat trim)	1915-20	1 25	BO	
164	7240	Rail (rear seat trim)	1915-20	1 25	BO	
166	7204	Rail (front top) R.	1915-20	45	BO	
167	7205	Rail (front top) L.	1915-20	45	BO	
168	7295	Retainer (rear floor board)	1915-19	15	BO	
169	7291	Riser (front floor board) R.	1915-20	30	BO	
170	7292	Riser (front floor board) L.	1915-20	30	BO	
171	5176	Riser (rear seat frame) R.	1918-19	35	BO	
172	5177	Riser (rear seat frame) L.	1918-19	35	BO	
173	5191	Riser (rear seat frame) rear	1918-19	60	BO	
174	8160	Sill assem. (rear end) T. C.	1915-17 and 20	2 40	BO	
175	5163	Sill assem. (rear end) T. C.	1918-19	1 00	BO	
176	8050	Sill (end) Torp.	1915-20	1 00	BO	
177	7175	Sill assem.—R., T. C.	1915-20	3 50	BO	
178	7178	Sill assem.—L., T. C.	1915-20	3 50	BO	
179	8462	Sill assem. (rear side) R., Torp.	1915-20	5 40	BO	
180	8463	Sill assem. (rear side) L., Torp.	1915-20	5 40	BO	
181	8063	Spring (front cushion) T. C.	1915-20	2 50	BO	
182	8063	Spring (front cushion) Torp. for metal frame	1917-20	2 50	BO	
183	5671	Spring (front cushion) Torp. for wood frame	1915-16 and 20	2 50	BO	
184	8151	Spring (front back) T. C.	1916-20	1 50	BO	
185	8336	Spring (seat back) Torp.	1915-20	2 00	BO	

Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

Part. No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
TOURING AND TORPEDO BODY—Continued						
186	8152	Spring (rear back) T. C.	1916-20	\$ 2 00		BO
187	5670	Spring (rear cushion) T. C.	1914-20	3 00		BO
188	5454	Strap (door)	1913-20	15		BO
189	7138	Strainer (rear seat)	1915-20	40		BO
190	7124	Strip (cowl finishing)	1915-19	30		BO
191	7225	Strip (front seat side trim) T. C.	1915-20	15		BO
192	7226	Strip (front seat rear trim) T. C.	1915-20	15		BO
193	7227	Strip (front seat corner trim) T. C.	1915-20	10		BO
194	7228	Strip (rear seat side trim) R.	1915-17 and 20	10		BO
195	8012	Strip (rear seat side trim) L.	1915-17 and 20	10		BO
196	5150	Strip (rear seat side trim)	1918-19	15		BO
197	7229	Strip (rear seat rear trim)	1915-17 and 20	15		BO
198	5149	Strip (rear seat rear trim)	1918-19	15		BO
199	7230	Strip (rear seat corner trim)	1915-17 and 20	10		BO
200	5147	Strip (rear seat corner trim)	1918-19	10		BO
201	7219	Strip (panel trim)	1915-20	10		BO
202	7220	Strip (panel trim)	1915-20	10		BO
203	7152	Strip (front seat panel and heel board ret.)	1915-20	15		BO
204	8395	Strip (rear seat back panel batten)	1916-20	15		BO
205	7153	Support (trim rail)	1915-20	20		BO
206	8077	Upholstering assem. (front seat back)	1915-20	7 50		
207	8078	Upholstering assem. (rear seat back)	1915-20	7 50		
208	8083	Upholstering assem. (blind door)	1915-20	60		BO
209	8084	Upholstering assem. (front) R.	1915-20	30		BO
210	8085	Upholstering assem. (front door) R.	1915-20	45		BO
211	8086	Upholstering assem. (rear door) R.	1915-20	45		BO
212	8087	Upholstering assem. (rear door) L.	1915-20	45		BO

Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.





5G Body

TORPEDO BODY

Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
COUPELET BODY						
214	9127	Anti-rattler (door window) upper	1915	\$ 0 05		BO
215	9455	Anti-rattler (door window) lower, Cp. Sn.	1915-20	01		BO
216	9147	Ball (top lock cam)	1915-16	02		BO
217	9932	Beading (roof)	1919-20	7 50		BO
218	9700	Bolt (det. pillar lock clamp)	1917-19	25		BO
219	9175	Bow (rear main)	1916	9 75		BO
220	9660	Bow (middle aux.)	1915-16	1 50		BO
221	9176	Bow assem. (middle aux.)	1915-16	9 30		BO
222	9458	Brace (front pillar) R.	1915-20	30		BO
223	9459	Brace (front pillar) L.	1915-20	30		BO
224	9105	Bracket (hand rail) Cp. Tn. Sn.	1915-20	15		BO
225	6927	Bumper (door) Cp. Tn. Sn.	1915-20	10		BO
226	6932	Bumper (roof rail) Cp. Sn.	1915-20	10		
227	9486	Bumper (deck door)	1916-20	10		BO
228	7260	Bracket (dash lamp)	1915-19	30		
229	9581	Cam (top lock) R.	1916	30		BO
230	9582	Cam (top lock) L.	1916	30		BO
231	9054	Carpet (floor)	1915-20	7 00		BO
232	9101	Casing (door bumper) Cp. Tn. Sn.	1915-20	15		BO
233	9768	Channel (back glass rubber)	1918-20	85		BO
234	9647	Channel (door glass up. rubber)	1916-19	40		BO
235	9071	Cord (blue binding) Cp. 1915 Tn.	1915-18	03yd		NT
235B	10309	Cord (seaming) (Sedan 1915-20)	1918-20	40yd		
236	9185	Cowl	1915-19	12 00		BO
236B	9185B	Cowl	1920	10 00		BO
237	9462	Cushion (window) Cp. Tn. Sn.	1915-20	10		BO
238	9621A	Cushion (seat) (imitation leather)	1916-17	\$15 00	20 00	BO
239	9621B	Cushion (seat) (whipcord) (Sn. 1920)	1918-20	14 00	17 50	BO
240	9160	Cushion (rear prop.)	1915-16	35		BO
241	9583	Covering (bow metal) R.	1916	70		BO
242	9584	Covering (bow metal) L.	1916	70		BO
242B	10645	Door (battery trap)	1920	75		BO
243	9586	Door less window—R.	1915-16	25 00	32 00	BO
244	9585	Door less window—L.	1915-16	25 00	32 00	BO
245	9797	Door less window—R.	1917	32 00	40 00	BO
246	9798	Door less window—L.	1917	32 00	40 00	BO
247	9886	Door less window—R.	1918-19	35 00	45 00	BO
247B	10700	Door less window—R.	1920	35 00	45 00	BO
248	9887	Door less window—L.	1918-19	35 00	45 00	BO
248B	10701	Door less window—L.	1920	35 00	45 00	BO
249	9946	Door assem. (deck)	1916-20	10 00		BO
250	9152	Dowel and plate (falling pillar)	1915-16	75		BO
252	9703	Ferrule (door grip)	1917-20	45		BO
253	9463	Ferrule (falling pillar)	1915-16	15		BO

Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT" if any) 20/21 represents the price of the goods.

Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
COUPELET BODY—Continued						
254	9464	Filler (door dove-tail socket)	1915-19		\$ 0 02	BO
255	9111	Flapper assem. (door window) Front R.	1915-19		2 00	BO
256	9112	Flapper assem. (door window) Front L.	1915-19		2 00	BO
257	9113	Flapper assem. (door window) Rear R.	1915-19		2 00	BO
258	9114	Flapper assem. (door window) Rear L.	1915-19		2 00	BO
259	9180	Frame (back glass) Cp. 1915-16 Tn.	1915-18		2 45	BO
260	9906	Frame (back glass)	1917		2 50	BO
261	9907	Frame (back glass)	1918-20		2 50	BO
262	9931	Frame assem. (roof)	1917-19	\$19 00	25 00	BO
262B	8649B	Garnish (door) R.	1921		1 00	BO
262C	8670B	Garnish (door) L.	1921		1 00	BO
262D	8649A	Garnish (door) R.	1919-20		1 25	BO
262E	8679A	Garnish (door) L.	1919-20		1 25	BO
263	9622	Glass (door window) 19 $\frac{1}{8}$ " x 21 $\frac{1}{2}$ "	1916		7 50	NT
265	9836	Glass (door window) 21" x 21 $\frac{1}{8}$ "	1917-19		6 50	NT
265B	8127	Glass (door window) 20 $\frac{3}{8}$ " x 21 $\frac{1}{8}$ "	1920		8 50	NT
266	9566	Glass (side window) 3 $\frac{1}{2}$ " x 7 $\frac{1}{16}$ " oval	1916		20	NT
267	9705	Glass (side window) 12 $\frac{3}{16}$ " x 20 $\frac{3}{8}$ "	1917		4 00	NT
268	9864	Glass (side window) 12 $\frac{1}{16}$ " x 21 $\frac{1}{8}$ "	1918-19		4 00	NT
268B	8039	Glass (side window) 12 $\frac{1}{16}$ " x 20 $\frac{1}{16}$ "	1920		6 00	NT
269	9053	Glass (back window) Cp. Tn. 7" x 22 $\frac{1}{2}$ " oval	1915-16		3 50	NT
270	9704	Glass (back window) 9 $\frac{5}{8}$ " x 26 $\frac{1}{2}$ " oval	1917		3 50	NT
271	9885	Glass (back window) 11 $\frac{1}{2}$ " x 26 $\frac{1}{2}$ " oval	1918-20		3 50	NT
272	9057	Handle (door lock lever) Cp. Tn. Sn.	1915-19		20	BO
273	9058	Handle (door lock) outside black Cp. Tn. Sn.	1915-18		1 25	BO
273B	9058B	Handle (door lock) outside nickel Cp. Sn.	1919-20		1 75	BO
274	9148	Handle (top lock)	1915-16		25	BO
274B	10543	Header (door) R.	1920		2 00	BO
274C	10544	Header (door) L.	1920		2 00	BO
275	9481	Hinge (deck door)	1916-20		75	BO
278	9579A	Hinge (door lower) L. Briggs	1920		70	BO
278B	9579B	Hinge (door lower) L. Fisher	1915-20		70	BO
278C	8636A	Hinge (door lower) R. Briggs	1920		70	BO
278D	8636B	Hinge (door lower) R. Fisher	1915-20		70	BO
279	9746	Hinge (door upper) R.	1916-19		70	BO
279B	8630A	Hinge (door upper) R. Briggs	1920		70	BO
279C	8630B	Hinge (door upper) R. Fisher	1920		70	BO
280	9747	Hinge (door upper) L.	1916-19		70	BO
280B	8631A	Hinge (door upper) L. Briggs	1920		70	BO
280C	8631B	Hinge (door upper) L. Fisher	1920		70	BO
281	9748	Hinge (door middle) R.	1916-19		70	BO
281B	8624A	Hinge (door middle) R. Briggs	1920		70	BO
281C	8624B	Hinge (door middle) R. Fisher	1920		70	BO
282	9749	Hinge (door middle) L.	1916-19		70	BO
282B	8625A	Hinge (door middle) L. Briggs	1920		70	BO

Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
COUPELET BODY—Continued						
282C	8625B	Hinge (door middle) L. Fisher	1920		\$ 0 70	BO
283	9131	Hinge (seat lid)	1915-19		05	BO
283B	5349	Hinge (seat lid)	1910-20		05	BO
284	9154	Hinge (falling pillar)	1915-16		2 50	BO
285	9744	Hinge (det. pillar up. half) R.	1917-19		50	BO
286	9745	Hinge (det. pillar up. half) L.	1917-19		50	BO
287	9178	Iron (bow slat) Cp. 1915 Tn.	1915-19		50	BO
288	9539	Iron (bow slat)	1916		70	BO
289	9171	Joint (short prop.) R.	1915-16		30	BO
290	9172	Joint (short prop.) L.	1915-16		30	BO
291	9173	Joint (long prop.) R.	1915-16		3 00	BO
292	9174	Joint (long prop.) L.	1915-16		3 00	BO
293	9484	Key (deck door)	1916-20		15	NT
294	9128	Knob (door window vent.) Cp. Tn. Sn.	1915-20		10	BO
295	9070	Lace (blue pasting) Cp. 1915 Tn.	1915-18		25yd	NT
296	9628	Lace (green pasting)	1916-17		25yd	NT
297	10342	Lace (gray pasting) Cp. 1918-20 Sn.	1915-20		30yd	BO
299	9589	Leather (deck and quarter) with pads	1916		13 00	BO
300	9590	Leather—R.	1916		6 00	BO
301	9591	Leather—L.	1916		6 00	BO
302	9588	Leather assembly (back)	1916	\$15 00	20 00	BO
303	9687	Leather complete (collapsible top)	1916	18 00	25 00	BO
304	9725	Leather (upper back panel)	1917		5 25	BO
305	9726	Leather (roof)	1917	16 50	24 00	BO
306	9936	Leather (roof)	1919-20		13 00	BO
307	9182	Lever (door lock) Cp. Tn. Sn.	1915-19		15	NT
307B	9182B	Lever (door lock) Cp. Sn.	1920		35	BO
308	9130	Lid (seat)	1915-20		3 00	BO
309	9551	Lifter (door window leather)	1915-17		3 00	BO
310	9551B	Lifter (door window whipcord)	1918-20		3 00	BO
311	9916	Lifter (side window leather)	1917		3 00	BO
312	9917	Lifter (side window whipcord)	1918-20		3 00	BO
313	9200	Lining (blue) Cp. 1915 Tn.	1915-18		3 50yd	NT
314	9552	Lining (green)	1916-17		3 50yd	NT
315	9898	Lining only (green)	1916		16 00	BO
316	9919	Lining only (green)	1917		7 00	BO
317	10270	Lining (whipcord) Cp. 1918-20 Sn.	1915-20		6 00yd	BO
318	9956	Lining (whipcord head)	1918-20		7 00	BO
319	9482	Lock (deck door)	1916-20		60	BO
320	9051	Lock less handle (door) L. Sn.—R. Cp. Tn.	1915-19		1 25	BO
320B	9051B	Lock less handle (door) L. Sn.—R. Cp.	1920		1 25	BO
321	9052	Lock less handle (door) R. Sn.—L. Cp. Tn.	1915-19		1 25	BO
321B	9052B	Lock less handle (door) R. Sn.—L. Cp.	1920		1 25	BO
322	9068	Lock complete (top) R.	1915-16		1 75	BO
323	9069	Lock complete (top) L.	1915-16		1 75	BO


Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
COUPELET BODY—Continued						
324	9141	Lock (top male) R.	1915-16	\$ 0 45	BO	
325	9142	Lock (top male) L.	1915-16	45	BO	
326	9143	Lock (top female) R.	1915-16	1 00	BO	
327	9144	Lock (top female) L.	1915-16	1 00	BO	
328	9710	Lock (det. pillar roof)	1917-19	30	BO	
329	9711	Lock (det. pillar upper end)	1917-19	40	BO	
331	9467	Moulding (door window) R.	1916-19	1 00	BO	
332	9468	Moulding (door window) L.	1916-19	1 00	BO	
333	9941	Moulding (side window)	1917-19	1 15	BO	
334	9929	Moulding (side window side)	1917-19	1 15	BO	
335	9713	Moulding (deck door opening)	1916-20	1 15	BO	
336	9719	Moulding (roof drip)	1917-20	3 20	BO	
337	9720	Nut (det. pillar clamp bolt)	1917-19	30	BO	
338	9088	Nut (top lock)	1915-16	15	BO	
339	9077	Nut (prop.) Cp. 1915-16 Tn.	1915-18	05	BO	
340	9601	Pad (window sash) Cp. Tn. Sn.	1915-19	50		
341	9184	Pawl (door lock plunger) Cp. Tn. Sn.	1915-20	10	NT	
342	9186	Panel (door) R.	1915-16	2 75	BO	
343	9187	Panel (door) L.	1915-16	2 75	BO	
344	9721	Panel (door) R.	1917-19	6 00	BO	
344B	9721B	Panel (door) R.	1920	6 00	BO	
345	9722	Panel (door) L.	1917-19	6 00	BO	
345B	9722B	Panel (door) L.	1920	6 00	BO	
346	9188	Panel (side) R.	1915-16	4 00	BO	
347	9189	Panel (side) L.	1915-16	4 00	BO	
348	9723	Panel (side) R.	1917-19	11 00	BO	
348B	9723B	Panel (side) R.	1920	12 50	BO	
349	9724	Panel (side) L.	1917-19	11 00	BO	
349B	9724B	Panel (side) L.	1920	12 50	BO	
350	9190	Panel (back lower)	1915-19	8 50	BO	
350B	9190B	Panel (back lower)	1920	8 50	BO	
351	9945	Panel (back upper)	1918-19	12 00	BO	
351B	9945B	Panel (back upper)	1920	12 00	BO	
352	9191	Panel (deck) R.	1915-20	4 50	BO	
353	9192	Panel (deck) L.	1915-20	4 50	BO	
354	9469	Panel (deck rear) below door	1916-20	3 50	BO	
355	9954	Panel (roof)	1918-19	11 00	BO	
356	9654	Pin (door hinge) Cp. Sn.	1915-20	03	BO	
357	9479	Pin (window lifter) Cp. Tn. Sn.	1915-20	03	BO	
357B	10540	Pillar (door hinge) in door—R.	1920	5 00	BO	
357C	10541	Pillar (door hinge) in door—L.	1920	5 00	BO	
357D	10538	Pillar (door lock) in door—R.	1920	5 00	BO	
357E	10539	Pillar (door lock) in door—L.	1920	5 00	BO	
358	9648	Pillar (falling) R.	1915-16	2 00	BO	
359	9652	Pillar (falling) L.	1915-16	2 00	BO	


Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
COUPELET BODY—Continued						
360	9649	Pillar (front up.) R.	1915-16	\$ 2 50	BO	
361	9653	Pillar (front up.) L.	1915-16	2 50	BO	
362	9650	Pillar (front low) R.	1915-16	2 50	BO	
363	9651	Pillar (front low) L.	1915-16	2 50	BO	
364	9489	Pillar assem. (front) R.	1915-16	5 00	BO	
365	9490	Pillar assem. (front) L.	1915-16	5 00	BO	
366	9736	Pillar (front) R.	1917	5 00	BO	
367	9737	Pillar (front) L.	1917	5 00	BO	
368	9939	Pillar (front) R.	1918-19	8 50	BO	
369	9940	Pillar (front) L.	1918-19	8 50	BO	
370	9769	Pillar (rear) R.	1917	4 00	BO	
371	9770	Pillar (rear) L.	1917	4 00	BO	
372	9965	Pillar (rear) R.	1918-19	5 00	BO	
373	9966	Pillar (rear) L.	1918-19	5 00	BO	
374	9730	Pillar assem. (det. top lock) R.	1917	10 50	BO	
375	9760	Pillar assem. (det. top lock) L.	1917	10 50	BO	
376	9943	Pillar assem. (det. top lock) R.	1918-19	10 50	BO	
377	9944	Pillar assem. (det. top lock) L.	1918-19	10 50	BO	
378	9106	Plate (door sill) R.	1915-18	80	BO	
379	9107	Plate (door sill) L.	1915-18	80	BO	
380	9727	Plate (door sill) R.	1919-20	80	BO	
381	9728	Plate (door sill) L.	1919-20	80	BO	
382	9741	Plate (door lever handle) Cp. Sn.	1918-19	15	BO	
383	9055	Plate (door lock lever) R. Cp. Tn.—L. Sn.	1915-19	15	BO	
384	9056	Plate (door lock lever) L. Cp. Tn.—R. Sn.	1915-19	15	BO	
385	6879	Plate (window lifter riveting) Cp. Tn. Sn.	1915-20	15	BO	
386	9073	Plate (window lifter strap) Cp. Tn. Sn.	1915-20	05		
387	9487	Plate (deck door bumper)	1916-20	06	BO	
388	9153	Plate (falling pillar dowel)	1915-16	30	BO	
389	9194	Plate (top lock) R.	1915-16	20	BO	
390	9195	Plate (top lock) L.	1915-16	20	BO	
400	7590	Plunger (door lock) R. Cp. Tn. L. Sn.	1915-20	25	BO	
401	9454	Plunger (door lock) L. Cp. Tn. R. Sn.	1915-20	25	BO	
402	9470	Plunger (door dove-tail)	1915-19	10	BO	
403	9948	Post (door hinge) R.	1915-16	8 00	BO	
404	9950	Post (door hinge) L.	1915-16	8 00	BO	
405	9771	Post (body hinge) R.	1917-19	7 00	BO	
406	9772	Post (body hinge) L.	1917-19	7 00	BO	
407	9155	Prop. (falling pillar) R.	1915-16	70	BO	
408	9156	Prop. (falling pillar) L.	1915-16	70	BO	
409	9161	Prop. (roof rail) R.	1915-16	25	BO	
410	9165	Prop. (roof rail) L.	1915-16	25	BO	
411	9157	Prop. (rear) R. Cp. 1915-16 Tn.	1915-18	1 25	BO	
412	9158	Prop. (rear) L. Cp. 1915-16 Tn.	1915-18	1 25	BO	
413	9822	Rail (hand) Cp. Tn. Sn.	1916-20	1 00	BO	

Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.



COUPELET BODY



Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
COUPELET BODY—Continued						
414	9170	Rail assem. (roof)	1915-16	\$ 8 75		BO
415	9761	Rail (roof) R.	1917-19	7 50		BO
415B	10554	Rail (roof) R.	1920	7 50		BO
416	9762	Rail (roof) L.	1917-19	7 50		BO
416B	10555	Rail (roof) L.	1920	7 50		BO
417	10553	Rail (roof) front	1917-20	3 50		BO
418	10556	Rail (roof) rear	1917-20	5 00		BO
419	9168	Retainer (prop. nut) Up. Cp. 1915-16 Tn.	1915-18	05		BO
420	9169	Retainer (prop. nut) Lower Cp. 1915-16 Tn.	1915-18	05		BO
421	9181	Retainer (head lining)	1915-16	45		BO
422	9908	Retainer (back glass)	1917	1 00		BO
423	9905	Retainer (back glass)	1918-20	1 00		BO
424	9140	Retainer (seat cushion) inc. leather	1915-20	1 00		BO
425	9930	Roof assem.	1917	\$28 00	35 00	BO
426	9955	Roof assem.	1918	25 00	33 00	BO
427	9933	Roof assem.	1919	36 00	45 00	BO
427B	9934	Roof assem.	1920	37 50	47 50	BO
428	9624	Sash (door window)	1916	6 00		BO
429	9739	Sash (door window)	1917	6 00		BO
430	9838	Sash (door window) R.	1918-19	7 50		BO
430B	8466	Sash (door window) R.	1920	7 50		BO
431	9839	Sash (door window) L.	1918-19	7 50		BO
431B	8467	Sash (door window) L.	1920	7 50		BO
432	9731	Sash (side window) R.	1917	6 00		BO
433	9732	Sash (side window) L.	1917	6 00		BO
434	9914	Sash (side window) R.	1918-19	7 50		BO
435	9915	Sash (side window) L.	1918-19	7 50		BO
435B	9997	Sash (side window)	1920	7 50		BO
436	1473	Screw (dash lamp bracket)	1915-19	02		NT
436B	10665	Sill assembly (side) R.	1920	13 50		BO
436C	10666	Sill assembly (side) L.	1920	13 50		BO
437	9475	Socket (door dove-tail)	1915-19	15		BO
438	8122B	Spring (seat cushion) (Sn. 1920)	1915-20	4 50		BO
439	9938	Spring (back cushion)	1915-20	4 00		BO
440	9183	Spring (door lock lever) Cp. Tn. Sn.	1915-20	05		NT
441	9146	Spring (top lock)	1915-16	05		BO
442	9059	Strap (door check) Cp. Tn. Sn.	1915-20	50		
443	9593	Strap (rear prop.)	1916	75		BO
444	9163	Strap (rear prop.) buckle end Cp. Tn.	1915-16	30		BO
445	9060	Striker (door lock) Cp. Tn. Sn.	1915-20	30		BO
446	9485	Striker (deck door lock)	1916-20	10		BO
447	9488	Support (deck door)	1916-20	30		BO
448	9625	Top assem. (collapsible)	1916	85 00	100 00	BO
449	8518	Upholstering (cowl) R.	1915-19	1 25		BO
450	8519	Upholstering (cowl) L.	1915-19	1 25		BO

Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
COUPELET BODY—Continued						
451	8520	Upholstering (cowl) Upper	1915-19	\$ 2 25		BO
452	9695	Upholstering (door leather) R.	1915-17	5 00		
453	9696	Upholstering (door leather) L.	1915-17	5 00		
454	9902	Upholstering (door whipcord) R.	1918-20	7 00		BO
455	9903	Upholstering (door whipcord) L.	1918-20	7 00		BO
456	9580	Upholstering assem. (seat back leather)	1916-17	16 85		BO
457	9921	Upholstering assem. (seat back whipcord)	1918-19	12 00		BO
458	9896	Upholstering (seat side) R.	1916-17	2 50		BO
458B	9896B	Upholstering (quarter panel) R.—Whipcord	1919-20	3 25		
459	9897	Upholstering (seat side) L.	1916-17	2 50		BO
459B	9897B	Upholstering (quarter panel) L.—Whipcord	1919-20	3 25		
461	9623	Window (door)	1915-16	14 00		BO
462	9738	Window (door)	1917	14 00		BO
463	9883	Window (door) R.	1918-19	16 00		BO
463B	8379	Window (door) R.	1919-20	17 00		BO
464	9884	Window (door) L.	1918-19	16 00		BO
464B	8402	Window (door) L.	1919-20	17 00		BO
465	9734	Window (side) R.	1917	10 00		BO
466	9735	Window (side) L.	1917	10 00		BO
467	9894	Window (side) R.	1918-19	12 50		BO
468	9895	Window (side) L.	1918-19	12 50		BO
469	8415	Window (side)	1920	10 50		BO
SEDAN BODY						
472	9668	Back assem. (pass. seat) metal only	1917-20	3 75		
473	9679	Back assem. (pass. seat) with uphol.	1917-20	17 00		
474	9618	Back assem. (driver's seat) metal only (pass. 1916)	1916-20	3 75		
475	9825	Base (driver's seat)	1916-20	5 50		
476	9681	Back assem. (driver's seat) with uphol. (pass. 1916)	1916-20	17 00		BO
477	8162	Board (1st floor)	1916-20	75		BO
478	8163	Board (2nd floor)	1916-20	75		BO
479	8164	Board (3rd floor) up	1916-20	35		
480	8165	Board (3rd floor) lower	1916-20	60		BO
481	9495	Board assem. (1st floor)	1916-20	1 25		BO
482	9496	Board assem. (2nd floor)	1916-20	1 25		BO
483	8169	Board assem. (3rd floor)	1916-20	2 25		BO
484	7914	Bolt (dash lamp bracket)	1915-19	10		NT
485	10085	Bow (roof)	1915-20	1 00		BO
487	9535	Brace (hinge pillar)	1915-20	75		BO
489	9502	Brace (rear pillar) R.	1916-20	75		BO
490	9503	Brace (rear pillar) L.	1916-20	75		BO
491	9845A	Bracket (curtain roller plain) Ford design	1915-20	30		BO
491B	9845B	Bracket (curtain roller plain) Fisher design	1915-20	30		BO
491C	9845C	Bracket (curtain roller plain) Curtain Supply Co. design	1915-20	30		BO


Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
SEDAN BODY—Continued						
491D 9845D		Bracket (curtain roller plain) Stewart Hartshorn design	1915-20		\$ 0 30	BO
492 9846A		Bracket (curtain roller notched) Ford design	1915-20		30	BO
492B 9846B		Bracket (curtain roller notched) Fisher design	1915-20		30	BO
492C 9846C		Bracket (curtain roller notched) Curtain Supply Co. design	1915-20		30	BO
492D 9846D		Bracket (curtain roller notched) Stewart Hartshorn design	1915-20		30	BO
493 7258		Bracket (dash lamp)	1915-19		30	
494 9211		Bumper (door sill plate) Tn. Sn.	1915-20		05	BO
496 9669		Carpet (floor)	1916-20		16 00	BO
497 9296		Carpet (front panel) R.	1915-20		1 75	
498 9697		Carpet (front panel) L.	1915-20		1 75	
499 9506		Channel (back window glass)	1915-20		45	BO
500 9673		Cloth (door and window curtain)	1915-20		3 25	
501 9674		Cloth (back curtain)	1915-20		3 25	
502 9247		Cord (window curtain)	1915-20		10yd BO	
503 9283		Cowl	1915-20	\$12 00	16 00	BO
504 10300		Curtain—R. or L.	1915-20		2 50	
505 10366		Curtain—back	1915-20		5 50	
508 9682		Cushion (rear seat)	1916-19	12 00	16 00	
509 9508		Cushion (pass. seat)	1916	11 50	15 00	BO
510 9678		Cushion (pass. seat)	1917-20		12 00	
511 9507		Cushion (driver's seat)	1916	11 50	15 00	BO
512 9680		Cushion (driver's seat)	1917-20		12 00	
512B 2069		Cushion (steering column)	1920		05	
513 9560		Door less window—R.	1915-18	35 00	45 00	BO
513B 9560B		Door less window—R. (striped)	1919-20	35 00	45 00	BO
514 9561		Door less window—L.	1915-18	35 00	45 00	BO
514B 9561B		Door less window—L. (striped)	1919-20	35 00	45 00	BO
514B 10074		Door (battery trap)	1919-20		75	BO
515 9519		Frame (back glass). Specify Fisher or Wadsworth	1915-19		2 50	BO
515B 10061		Frame (rear seat rear)	1915-20		2 25	BO
515C 9813		Felt (window sash)	1915-20		50	BO
516 9214		Glass (door) 19 $\frac{3}{4}$ "x23 $\frac{1}{8}$ "	1915-20		7 50	NT
517 9513		Glass (front window) 17 $\frac{1}{4}$ "x23 $\frac{1}{8}$ "	1916-20		5 50	NT
518 9514		Glass (rear window) 19 $\frac{3}{4}$ "x23 $\frac{1}{8}$ "	1916-20		7 50	NT
519 9257		Glass (back) 14 $\frac{1}{2}$ "x23 $\frac{1}{8}$ " oval	1915-20		5 50	NT
519B 5361		Glass (back) 14 $\frac{3}{8}$ "x23 $\frac{1}{8}$ " oval	1918-20		5 50	NT
520 10062		Header (front window up.) R. Specify Wadsworth or Fisher	1915-20		2 00	BO
521 10063		Header (front window up.) L. Specify Wadsworth or Fisher	1915-20		2 00	BO
522 10059		Header (door window up.) R. Specify Wadsworth or Fisher	1915-20		2 00	BO


Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
SEDAN BODY—Continued						
523 10060		Header (door window up.) L. Specify Wadsworth or Fisher	1915-20		\$ 2 00	BO
524 10056		Header (rear window up.) R. Specify Wadsworth or Fisher	1915-20		2 00	BO
525 10057		Header (rear window up.) L. Specify Wadsworth or Fisher	1915-20		2 00	BO
526 9202		Hinge (door up.) R.	1915-20		45	BO
527 9203		Hinge (door up.) L.	1915-20		45	BO
528 9204		Hinge (door middle) R.	1915-20		50	BO
529 9205		Hinge (door middle) L.	1915-20		50	BO
530 9206		Hinge (door lower) R.	1915-20		60	BO
531 9207		Hinge (door lower) L.	1915-20		60	BO
532 9516		Leg assem. (pass. seat) R.	1916		1 50	BO
533 9517		Leg assem. (pass. seat) L.	1916		1 50	BO
534 9664		Leg assem. (pass. seat) R.	1917-19		1 50	BO
534B 9664B		Leg assem. (pass. seat) R.	1920		1 60	
535 9665		Leg assem. (pass. seat) L.	1917-19		1 50	BO
535B 9665B		Leg assem. (pass. seat) L.	1920		1 60	
538 9518		Leg (pass. seat front)	1916		35	
539 9780B		Leg (pass. seat front)	1917-20		70	BO
540 9666		Leg (pass. seat rear)	1917-19		90	BO
541 9606		Lifter (rear window)	1915-20		3 00	
543 9608		Lifter (door window)	1915-20		3 00	
544 9555		Lining (gray)	1915-16		5 75yd	NT
545 9540		Lining (head)	1915-20		14 00	
547 9217		Moulding (front qr. window front)	1915-19		1 20	BO
548 9218		Moulding (front qr. window rear)	1915-19		1 25	BO
549 9219		Moulding (front qr. window upper)	1915-19		1 20	BO
550 9220		Moulding (front qr. window lower)	1915-19		1 20	BO
551 9221		Moulding (rear qr. window front)	1915-19		1 20	BO
552 9222		Moulding (rear qr. window rear)	1915-19		1 20	BO
553 10130		Moulding (rear qr. window upper)	1915-19		1 20	BO
554 10132A		Moulding (rear qr. window lower)	1915-19		1 20	BO
555 9297		Moulding (roof drip)	1915-20		4 00	BO
556 7923		Nut (dash lamp bracket bolt)	1915-19		05	NT
557 9074		Panel (roof)	1915-20		13 75	BO
558 9567		Panel (door) R.	1915-20		3 00	BO
559 9568		Panel (door) L.	1915-20		3 00	BO
560 9569		Panel (front) R.	1915-20		10 00	BO
561 9565		Panel (front) L.	1915-20		10 00	BO
562 9570		Panel (rear upper). Specify Fisher or Wadsworth	1915-20		12 75	BO
563 9571		Panel (rear lower) Fisher	1916-20		8 50	BO
564 8516		Panel (rear lower with quarter panels). Specify Fisher or Wadsworth	1916-20	\$18 00	25 00	BO
565 9876		Panel (rear qr.) R. Specify Fisher or Wadsworth	1916-20		13 00	BO

Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.



SEDAN BODY




SEDAN BODY PARTS

Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
SEDAN BODY—Continued						
566	9882	Panel (rear qr.) L. Specify Fisher or Wadsworth	1916-20		\$13 00	BO
567	9208	Plate (door sill) R.	1915-20		1 50	BO
568	9209	Plate (door sill) L.	1915-20		1 50	BO
568B	7667	Plate (steering column)	1919-20		05	
569	9098	Pillar (front) R. Specify Fisher or Wadsworth	1915-19		9 00	BO
570	9103	Pillar (front) L. Specify Fisher or Wadsworth	1915-19		9 00	BO
571	10003	Pillar (door hinge) R. Specify Fisher or Wadsworth	1915-19		6 00	BO
572	10004	Pillar (door hinge) L. Specify Fisher or Wadsworth	1915-19		6 00	BO
573	10009	Pillar (door lock) R. Specify Fisher or Wadsworth	1915-19		8 50	BO
574	10010	Pillar (door lock) L. Specify Fisher or Wadsworth	1915-19		8 50	BO
575	10011	Pillar (rear) R. Specify Fisher or Wadsworth	1915-19		6 00	BO
576	10012	Pillar (rear) L. Specify Fisher or Wadsworth	1915-19		6 00	BO
577	10021	Rail (roof) R. Specify Fisher or Wadsworth	1915-19		6 00	BO
578	10022	Rail (roof) L. Specify Fisher or Wadsworth	1915-19		6 00	BO
578B	10024	Rail (rear roof)	1915-20		2 00	BO
578C	10026	Rail (front roof)	1915-20		2 00	BO
579	9271	Retainer (pass. seat cushion)	1915-20		50	
580	9264	Retainer (rear seat cushion)	1915-20		50	
581	9758-A1	Roller assem. (side curtain) Ford design	1915-20		1 85	BO
581B	9758-A2	Roller assem. (side curtain) Fisher design	1915-20		1 85	BO
581C	9758-A3	Roller assem. (side curtain) Curtain Supply Co. design	1915-20		1 85	BO
581D	9758B	Roller assem. (side curtain) Stewart Hartshorn design	1915-20		1 85	BO
582	9759-A1	Roller assem. (back curtain) Ford design	1915-20		1 85	BO
582B	9759-A2	Roller assem. (back curtain) Fisher design	1915-20		1 85	BO
582C	9759-A3	Roller assem. (back curtain) Curtain Supply Co. design	1915-20		1 85	BO
582D	9759B	Roller assem. (back curtain) Stewart Hartshorn design	1915-20		1 85	BO
583	9627	Roof assem. Specify Fisher or Wadsworth	1915-20	\$28 00	36 00	BO
584	9686	Sash (door window) R.	1915-20		6 00	BO
585	9690	Sash (door window) L.	1915-20		6 00	BO
586	9598	Sash (front window) R.	1915-20		6 00	BO
587	9599	Sash (front window) L.	1915-20		6 00	BO
588	9604	Sash (rear window) R.	1915-20		6 00	BO
589	9605	Sash (rear window) L.	1915-20		6 00	BO
590	9629	Seat assem. (pass.)	1915-20	20 00	25 00	
591	9639	Seat assem. (driver's)	1916-20	27 00	35 00	
592	9856	Spring (curtain roller)	1915-20		50	BO
594	8122	Spring (rear seat cushion)	1915-19		6 00	BO
595	8123	Spring (driver's seat cushion)	1916-20		1 80	BO
596	8124	Spring (pass. seat cushion)	1917-20		1 80	BO

Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.


Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
SEDAN BODY—Continued						
597	9520	Support (driver's and pass. seat back) R.	1916-20		\$ 0 60	BO
598	9521	Support (driver's and pass. seat back) L.	1916-20		60	BO
599	7913	Screw (dash lamp bracket)	1915-19		02	NT
600	9246	Tack (curtain cord)	1915-20		05 1/2	BO
602	9698	Upholstering (front qr. panel) R. Specify year	1915-20		3 00	
603	9699	Upholstering (front qr. panel) L. Specify year	1915-20		3 00	
604	9609	Upholstering (rear seat back)	1916		13 00	
605	9634	Upholstering (rear seat back)	1917	\$16 50	22 50	BO
606	9683	Upholstering (rear seat back)	1918-19		16 00	BO
609	9612	Upholstering (door) R.	1916		5 25	BO
610	9613	Upholstering (door) L.	1916		5 25	BO
611	9684	Upholstering (door) R.	1917-20		5 25	
612	9685	Upholstering (door) L.	1917-20		5 25	
613	9750	Upholstering (cowl) R.	1915-20		1 25	
614	9751	Upholstering (cowl) L.	1915-20		1 25	
615	9752	Upholstering (cowl) upper	1915-20		2 25	BO
616	9661	Window (door) R.	1915-20		12 50	BO
617	9662	Window (door) L.	1915-20		12 50	BO
618	9596	Window (front qr.) R.	1915-20		11 50	BO
619	9597	Window (front qr.) L.	1915-20		11 50	BO
620	9602	Window (rear qr.) R.	1915-20		12 50	BO
621	9603	Window (rear qr.) L.	1915-20		12 50	BO
RADIATOR						
622	1155	Brace (side)	1909-16		05	
623	1125B	Bracket (rod on rad.)	1909-20		10	
624	1135B	Bottom (up. tank)	1909-16		1 50	
625	8706	Bottom (up tank)	1917-20		1 25	
626	1109B	Clasp (hood on rad.)	1909-20		02	
627	1133	Core	1909-16		16 50	
628	8770B	Core	1917-19		16 50	
629	1101B	Con. (inlet)	1909-16		30	
630	8712	Con. (inlet)	1917-20		25	
631	1104B	Con. (outlet)	1909-20		30	
632	1134B	Cover (lower tank)	1909-20		30	
633	1143	Fin	1909-20		10	
634	1102B	Flange (filler)	1909-16		50	
635	8713	Flange (filler)	1917-20		50	
637	1138B	Piece (front bottom)	1909-16		25	
638	1145B	Piece (front side) R.	1909-16		30	
639	1146B	Piece (front side) L.	1909-16		30	
640	1132	Pipe (overflow)	1909-16		30	BO
641	8718	Pipe (overflow)	1917-20		25	BO
642	8709	Plate (splash)	1917-20		15	
645	1126B	Support	1909-19		45	
645B	1126C	Support (truck—1919-20)	1920		45	

Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.



Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
RADIATOR—Continued						
646	1190	Support (lower tank)	1909-19	\$ 0	05	
646B	1190B	Support (lower tank) (truck—1919-20)	1920		05	
647	8750	Support (up. tank) R.	1917-20		15	
648	8751	Support (up. tank) L.	1917-20		15	
649	1113	Tank complete (top)	1909-16	5	00	
650	8723	Tank complete (top)	1917-20	4	00	
651	1137B	Tank (lower)	1909-20	1	00	
652	1136B	Top (up. tank) less filler flange	1909-16	1	50	
653	8705	Top (up. tank) less filler flange	1917-20		60	
654	1144	Tube	1909-16		06	BO
655	8717	Tube	1917-20		08	BO
656	1139B	Wall—L.	1909-16		60	
657	1140B	Wall—R.	1909-16		60	
658	1141	Wall (up. tank front)	1909-16		80	
659	8707	Wall (up. tank front)	1917-20		60	
660	1142B	Wall (up. tank rear)	1909-16		75	
661	8708	Wall (up. tank rear)	1917-20		40	
662	8872	Wall assem. (rear)	1917-20		90	
COIL PARTS						
663	5860	Back and false bottom	1914-19	1	00	
663B	5860B	Back and false bottom	1920	1	00	
664	5836	Bar (box bus)	1914-20		05	
665	5807	Bolt and spring (term.) R.	1914-20		10	
666	5808	Bolt and spring (term.) L.	1914-20		10	
667	5809	Bolt (term.)	1914-20		02	
668	1308	Bolt (box to dash)	1914-20		03	NT
668B	2852	Nut (box to dash bolt) (used on 668)	1914-20		02	NT
669	6736	Bridge and screw (lower)	1914-20		10	
670	6768	Collar (vib. bolt)	1914-20		02	
671	5852	Lock (box)	1914-20		10	
673	472B	Nut (term. bolt)	1914-20		02	NT
674	6754	Nut (vib. adj. bolt)	1914-20		02	NT
675	6772	Nut (vib. bolt)	1914-20		02	NT
676	5827A	Screw (switch fastening)	1914-17		01	NT
677	5827B	Screw (switch fastening)	1918-19		01	NT
677B	5832	Nut (switch fastening screw) (used on 677)	1918-19		01	NT
678	5810	Screw (switch cover)	1914-19		02	NT
679	6785	Screw (armature to lower bridge)	1914-20		01	
680	6782	Screw (lower bridge adj.)	1914-20		01	
681	6771	Screw (box back and bottom)	1914-20		02	NT
682	5811	Spring (term. bolt)	1914-20		03	
683	5812	Spring (term. bolt)	1914-20		03	
684	5810	Tube (term. bolt porcelain)	1914-20		10	BO
685	1034	Washer (box to dash bolt)	1914-20		01	NT
686	5831	Washer (term. bolt)	1914-20		01	NT

Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.



Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
COIL PARTS—Continued						
687	6749	Washer (vib. bolt insulator)	1914-20	\$ 0	05dz	
687B	6757B	Washer (vib. adj. bolt upper)	1914-20		05dz	
TOPS						
688	7940	Touring car top assem.		\$32 00	40 00	
689	7941	Runabout top assem.		25 00	33 00	
FORD CARBURETOR PARTS—1912-20 (MODEL "C")						
6041	6340	Mix. chamber	1914-20	3 25		BO
6042	4801	Mix. chamber top	1912-14-20		70	BO
6043	4808	Mix. chamber top screw	1912-20		02	BO
6044	6317	Mix. chamber top gasket	1914-20		02	BO
6044B	6367	Mix. chamber bottom gasket	1916-20		03	BO
6045	4810	Mix. chamber nut	1912-20		10	BO
6046A	6318	Float chamber and bush. assem.	1914-20		75	BO
6046B	6365	Float chamber and drain valve assem.	1917-20		50	BO
6047	6320	Float lever pin	1914-20		03	BO
6048	6321	Float valve seat	1914-20		10	BO
6049	6322	Float valve seat gasket (fibre)	1914-19		01	BO
6051	4812	Spray needle clamp nut	1912-20		05	BO
6052	6341	Spray nozzle	1914-20		30	BO
6053	4820	Spray nozzle gasket (fibre)	1912-14-20		02	BO
6055	4859	Gas. inlet elbow	1913-20		15	BO
6057	6360	Low speed tube with nut	1915-20		15	BO
6058	4814	Low speed tube retaining screw	1912-14-20		05	BO
6060	4816	Low speed boss screw	1912-14-20		05	BO
6061	4817	Strangling tube	1912-14-20		15	BO
6062	4818	Strangling tube retainer—open wire ring	1912-14-20		02	BO
6064	4520	Throttle lever stop screw	1911-20		02	NT
6065	4521	Throttle lever clamp screw	1911-19		02	NT
6068	4517	Throttle plate	1912-14-20		10	BO
6070	4836B	Throttle lever	1912-14-20		30	BO
6070B	4836	Throttle lever (oversize)	1912-14-20		30	BO
6071	4528	Throttle lever adj. lock nut	1911-20		02	NT
6074	6337	Aux. throttle plate	1915-20		05	BO
6076	6342	Aux. throttle lever spring	1914-20		02	BO
4494	3128	Aux. throttle lever spring	1910-14		05	BO
6077	6327	Aux. throttle lever assem.	1914-20		25	BO
4463	4805	Float lever holding screw nut	1912-19		02	BO
4464	4853	Float lever holding screw	1913-19		03	BO
6081A	6329	Drain valve plug and handle	1916-20		15	BO
HOLLEY CARBURETOR PARTS—(MODEL "NH")						
6202B	6365B	Float chamber and drain valve assem.	1920	1 00		BO
6203	555B	Gasket (float chamber)	1920		10	BO
6204	4820B	Gasket (spray nozzle)	1920		02	BO
6205	6367B	Gasket (mixer chamber)	1920		03	BO

Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT," if any) 20/21 represents the price of the goods and 1/21 represents excise tax.


Part No.	Fac. No.	NAME	YEAR	Net Price to Dealer	PRICE	Tax Status
----------	----------	------	------	---------------------	-------	------------

HOLLEY CARBURETOR PARTS—(MODEL "NH")—Continued

6206	4836B	Lever (throttle) (use 6070)	1920			BO
6207	6340B	Mixer chamber	1920	\$ 3 25		BO
6208	4812B	Nut (adjusting needle clamp)	1920	25		BO
6209	4517B	Plate (throttle)	1920	10		BO
6210	6320B	Pin (float lever)	1920	05		BO
6211	6284	Screw (float chamber)	1920	35		BO
6212	6321B	Seat (float valve)	1920	20		BO
6214	6341B	Spray nozzle (first 10,000)	1920	75		BO
6214B	6341C	Spray nozzle (after first 10,000)	1920	75		BO
6215	6273	Vent plug (air passage)	1920	15		BO

KINGSTON CARBURETOR PARTS—1913-20

6102	4873	Throttle lever	1913-20	40		BO
6103A	6382	Constant air supply lever and gate assem.	1913-20	60		BO
6104	3005	Gas. valve cap	1910-16	15		BO
6105A	6357	Air valve cap	1915-16	60		BO
6105B	8817	Air valve cap	1917-20	40		BO
6106	6350	Float chamber	1915-16	2 25		BO
6106A	6370	Float chamber	1917-20	1 00		BO
6107	6352	Mix. chamber	1915-16	3 25		BO
6107A	6371	Mix. chamber	1917-20	3 25		BO
6108	4872	Mix. chamber gasket	1913-16	15		BO
6108A	6374	Mix. chamber gasket	1917-20	15		BO
6109	3012	Throttle gate (use 6068)	1910-20			BO
6110	4571B	Constant air supply gate	1913-14	10		BO
6110A	6363	Constant air supply gate	1915-20	15		BO
6111	4883	Mix. chamber nut	1913-20	15		NT
6114	3027	Gas valve retainer nut	1910-16	10		BO
6116	4831	Pet cock	1915-20	25		BO
6117	6354	Primer	1915-16	30		BO
6118	3014	Float to lever and throttle gate screw	1910-16	01		BO
6118A	6379	Float to lever screw	1917-20	03		BO
6120	4875	Throttle lever adjusting screw	1913-20	03		NT
6121	3017	Throttle lever clamp screw	1910-20	03		BO
6122	3004B	Gas. valve operating lever shaft	1913-16	15		BO
6123	6381	Air valve shaft	1915-20	25		BO
6124A	6368	Spray needle sleeve	1915-20	25		BO
6125	4570B	Constant air supply spring	1913-20	03		BO
6126	6359	Float valve seat	1915-16	15		BO
6126A	6380	Float valve seat	1917-20	15		BO
6127	3002	Gas. valve	1910-16	35		BO
6128	6355	Air valve	1915-20	40		BO
6129	6361	Float valve seat gasket (fibre)	1915-16	03		BO
6129A	6373	Float valve seat gasket (fibre)	1917-20	03		BO



Of the net amount at which these parts are billed to purchasers that purchase direct from the Ford Motor Company (except parts marked "BO" or "NT" if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

Part No.	NAME	Net Price to Dealer	Tax Status
HEADLAMP BULBS			
6572X	Headlamp Mazda bulb (8-9 volt used with magneto) in lots of 50	\$14 70	BO
6572BX	Headlamp Mazda bulb in lots of 50	14 70	BO
6572CX	Headlamp Mazda bulb (6-8 volt single contact) in lots of 50	14 70	BO
6520X	Dimmer bulb (for head and tail lamp) 6-8 volt 2-ep. single contact, in lots of 50	8 23	BO

