

*Ford*

THE UNIVERSAL CAR

Price List  
of Body  
Parts

Model T

*Ford Motor Company*

DETROIT, MICHIGAN

## **IMPORTANT**

**INSIST** on getting **GENUINE** Ford Parts when your Ford car needs repairing. Don't allow "bogus" or imitation Parts to go in your car.



September 1st, 1923

---

Prices subject to change without notice

---


# PRICE LIST OF BODY PARTS Ford Model T

Effective September 1, 1923

NOTE—When ordering upholstery or parts which are upholstered, always send sample of material desired. Prices marked with an asterisk (\*) are subject to 25% discount to Dealers and 10% discount to Garages. All other prices are subject to the regular Dealers and Garage discounts. Panels, pillars, etc., are furnished unpainted and prices of these items as listed are for the unpainted parts.

Part No.	NAME	YEAR	PRICE	Tax Status
<b>TORPEDO BODY PARTS</b>				
8391X	Block (side arm trim) assy.	1915-22	\$ 0 05	
5144AX	Board (heel)	1915-22	1 50	
8329X	Board (tool box)	1915-22	40	
8354X	Cowl	1915-22	4 00	
7023X	Deck assy.	1914-22	11 00	
5116X	Door assy. (upholstered and painted)	1915-22	5 00	M H
5308X	Door (battery trap) assy.	1920-22	75	
8021X	Door (deck) assy.	1913-22	3 75	
5569X	Fastener (deck door) assy.	1913-22	25	
5458X	Floor (deck) assy.	1915-22	3 50	
7269X	Frame (door) assy.	1915-22	1 50	
8429X	Frame (seat side) R. H.	1917-22	30	
8430X	Frame (seat side) L. H.	1917-22	30	
8442X	Frame (seat rear)	1917-22	45	
5297X	Hinge (door) assy.	1914-22	40	
8431X	Iron (body top) long—R. H.	1917-22	45	
8432X	Iron (body top) long—L. H.	1917-22	45	
8401X	Iron (body top) short	1917-22	40	
5680X	Lock (door) assy.	1913-22	40	
6641X	Panel (deck side) R. H.	1914-22	90	
6642X	Panel (deck side) L. H.	1914-22	90	
7182X	Panel (door)	1915-22	1 25	
8132X	Panel (front side) R. H.	1915-22	2 00	
8133X	Panel (front side) L. H.	1915-22	2 50	
8024X	Panel (seat back)	1915-22	2 00	
6638X	Panel (seat side) R. H.	1914-22	2 50	
6639X	Panel (seat side) L. H.	1914-22	2 50	
8420X	Panel and frame (side) assy.—R. H.	1915-22	12 00	
8421X	Panel and frame (side) assy.—L. H.	1915-22	12 00	
7193AX	Pillar (dash) R. H.	1915-22	25	
7194AX	Pillar (dash) L. H.	1915-22	25	
7195AX	Pillar (panel) R. H.	1915-22	40	
7196AX	Pillar (panel) L. H.	1915-22	40	
7197AX	Pillar (seat) R. H.	1915-22	30	
7198AX	Pillar (seat) L. H.	1915-22	30	
5205X	Pin (door hinge)	1912-22	01	
8433X	Plate (lock striker)	1917-22	10	
7204AX	Rail (front top) R. H.	1915-22	35	
7205AX	Rail (front top) L. H.	1915-22	35	
7216X	Rail (seat trim) assy.	1915-22	1 00	
8334X	Rail (side top) R. H.	1915-22	10	
8053X	Rail (side top) L. H.	1915-22	10	
7291AX	Riser (floor board) R. H.	1915-22	30	
7292AX	Riser (floor board) L. H.	1915-22	30	
8050X	Sill (end)	1915-22	90	
8040X	Sill (side) assy.—R. H.	1915-22	3 00	
8041X	Sill (side) assy.—L. H.	1915-22	3 00	
5671X	Spring (cushion) for wood frame	1915-16 and 20	2 00	
8063X	Spring (cushion) for metal frame	1917-22	2 00	
8336X	Spring (seat back)	1915-22	1 25	
7208AX	Strainer (blind slide)	1915-22	10	
5454X	Strap (door)	1913-22	10	
7153X	Support (trim rail)	1915-22	15	
8083X	Upholstering (blind door) assy.	1915-22	40	
8075X	Upholstering (door) assy.	1915-22	30	
8084X	Upholstering (front) assy.	1915-22	15	
8077AX	Upholstering (seat back) assy.	1915-22	4 50	

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.



Note.—Where marked R. H. there is always a left hand of the same piece or vice versa.



Part No.	NAME	YEAR	PRICE	Tax Status
----------	------	------	-------	------------


### ROADSTER BODY PARTS

7375X	Board (heel) and finishing strip assy.	1922-23	4 10	
7775X	Brace (top iron) R.	1922-23	35	
7776X	Brace (top iron) L.	1922-23	35	
8458X	Bracket (seat frame to pillar) R. H.	1922-23	10	
8459X	Bracket (seat frame to pillar) L. H.	1922-23	10	
8417X	Bracket (seat back cushion frame)	1922-23	03	
8350BX	Cowl (assy.)	1922-23	3 00	
7023BX	Deck (assy.)	1922-23	10 00	
8021BX	Door (deck assy.)	1922-23	3 75	
5308X	Door (battery trap) assy.	1922-23	75	
5458BX	Floor (deck) assy.	1922-23	3 50	
7269X	Frame (door) assy.	1922-23	1 50	
8442BX	Frame (seat) rear	1922-23	35	
8429BX	Frame (seat) side—right	1922-23	20	
8430BX	Frame (seat) side—left	1922-23	20	
8454BX	Frame (side assy)—right	1922-23	6 50	
8455BX	Frame (side assy)—left	1922-23	6 50	
8434X	Frame (seat back cushion) assy.	1922-23	25	
5568BX	Hinge (deck door) assy.	1922-23	10	
5297X	Hinge (door) assy.	1922-23	40	
5178BX	Iron (body top) front—R. H.	1922-23	40	
5179BX	Iron (body top) front—L. H.	1922-23	40	
8484X	Key (deck lock)	1922-23	10	
5680X	Lock (door) assy.	1922-23	40	
9482X	Lock (deck) assy.	1922-23	25	
7751X	Panel (deck side) R. H.	1922-23		
7752X	Panel (deck side) L. H.	1922-23		
7753X	Panel (deck rear)	1922-23		
7800X	Panel (deck top) and hinge assy.	1922-23		
6641BX	Panel (rear side) R. H.	1922-23	35	
6642BX	Panel (rear side) L. H.	1922-23	35	
7772X	Panel (end sill)	1922-23	35	
7128X	Panel (door) L. H. control	1922-23	1 25	
6602BX	Panel (instrument)	1922-23	1 00	
8420BX	Panel (side and frame) assy.—R. H.	1922-23	15 00	
8421BX	Panel (side and frame) assy.—L. H.	1922-23	15 00	
7777X	Panel (back) and "T" moulding assy.	1922-23	2 25	
7778X	Panel (front side) and reinforcement assy.—R. H.	1922-23	4 50	
7779X	Panel (front side) and reinforcement assy.—L. H.	1922-23	4 50	
7193BX	Pillar (dash—right)	1922-23	25	
7194BX	Pillar (dash—left)	1922-23	25	
7195BX	Pillar (panel—right)	1922-23	40	
7196BX	Pillar (panel—left)	1922-23	40	
7797X	Pillar (seat—right)	1922-23	30	
7798X	Pillar (seat—left)	1922-23	30	
7444X	Plug (front side panel)	1922-23	05	
7204BX	Rail (front top) R. H.	1922-23	35	
7205BX	Rail (front top) L. H., L. H. C.	1922-23	35	
8053BRX	Rail (side top) L. H.	1922-23	30	
8053CX	Rail (side top) L. H.	1922-23	30	
8334BX	Rail (side top) R. H.	1922-23	15	
7785X	Rail (trim) center	1922-23	40	
8351X	Rail (side trim) assy.—R. H.	1922-23	65	
8352X	Rail (side trim) assy.—L. H.	1922-23	65	
7291BX	Riser (floor board) right	1922-23	20	
7292BX	Riser (floor board) left	1922-23	20	
8050BX	Sill (end)	1922-23	65	
8462BX	Sill (side) assy.—R. H.	1922-23	3 25	
8463BX	Sill (side) assy.—L. H.	1922-23	3 25	
8054X	Strainer (back panel)	1922-23	25	

### TOURING CAR BODY PARTS

8476BX	Bar (rear seat) metal	1915-17 and 20-22	65	
8387X	Block (side arm trim) assy.—front—R. H.	1915-21	05	
8391X	Block (side arm trim) assy.—front—L. H.	1915-21	05	
8388X	Block (side arm trim) assy.—rear—R. H.	1915-21	05	
8390X	Block (side arm trim) assy.—rear—L. H.	1915-21	05	
1604X	Board (floor) rear	1919-21	70	
5144AX	Board (front heel)	1915-21	1 50	
7375X	Board (front heel) and finishing strip assy.	1921-23	1 10	
8349AX	Board (rear heel) assy.	1916-21	2 00	
8349BX	Board (rear heel) and finishing strip assy.	1921-23	1 25	
7148AX	Board (rear seat toe) steel	1915-17 and 20-21	1 25	
7148BX	Board (rear seat toe) assy.	1921-23	75	
8372X	Bottom (front seat) assy.—steel	1915-17 and 20-21	1 75	
5131X	Bottom (front seat) assy.—wood	1918-19	90	
7143AX	Bottom (tool box)	1915-17 and 20-21	1 00	
7143BX	Bottom (tool box) assy.	1921-23	1 00	

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.




Part No.	NAME	YEAR	Tax PRICE STATUS
----------	------	------	------------------

TOURING CAR BODY PARTS—Continued

7420X	Brace (fender and top iron) assy.—R. H.	1921-23	\$ 1 00
7421X	Brace (fender and top iron) assy.—L. H.	1921-23	1 00
8191X	Brace (seat)	1916-21	05
8469X	Bracket (cowl to body) R. H.	1918-21	15
8470X	Bracket (cowl to body) L. H.	1918-21	15
8474X	Bracket (dash to pillar) R. H.	1917-21	25
8475X	Bracket (dash to pillar) L. H.	1917-21	25
7411X	Bracket (fender)	1921-23	10
7411X	Bracket (top iron)	1921-23	10
8350AX	Cowl	1915-21	4 00
8350BX	Cowl	1921-23	3 00
5116X	Door (front) assy. (upholstered and painted)	1915-21	5 00 M H
7118X	Door (rear) assy.—R. H. (upholstered and painted)	1915-21	5 00 M H
7119X	Door (rear) assy.—L. H. (upholstered and painted)	1915-21	5 00 M H
7269X	Frame (front door) assy.	1915-21	1 50
7149X	Frame (front seat center)	1915-21	35
7150AX	Frame (front seat side)	1915-21	25
7150BX	Frame (front seat side)	1921-23	25
7276X	Frame (rear door) assy.—R. H.	1915-21	1 50
7277X	Frame (rear door) assy.—L. H.	1915-21	1 50
8347X	Frame (rear seat) assy.—R. H.	1916-17 and 20-21	1 00
8348X	Frame (rear seat) assy.—L. H.	1916-17 and 20-21	1 00
7141AX	Frame (rear seat center)	1915-21	50
7141BX	Frame (rear seat center)	1921-23	25
7139AX	Frame (rear seat side) R. H.	1915-21	75
7139BX	Frame (rear seat side) R. H.	1921-23	40
7140AX	Frame (rear seat side) L. H.	1915-21	75
7140BX	Frame (rear seat side) L. H.	1921-23	40
5297X	Hinge (door) assy.	1915-23	40
5190CX	Iron (body top) rear seat—corner	1921-23	10
5190AX	Iron (body top) rear seat—corner—R. H.	1915-17 and 20-21	50
5190BX	Iron (body top) rear seat—corner—R. H.	1918-19	50
5189AX	Iron (body top) rear seat—corner—L. H.	1915-17 and 20-21	50
5189BX	Iron (body top) rear seat—corner—L. H.	1917-19	50
5178X	Iron (body top) rear seat—side—R. H.	1915-21	40
5178BX	Iron (body top) rear seat—side—R. H.	1921-23	40
5179X	Iron (body top) rear seat—side—L. H.	1915-21	40
5179BX	Iron (body top) rear seat—side—L. H.	1921-23	40
5145AX	Iron (top) front seat	1915-21	50
5145BX	Iron (top) front seat	1921-23	40
5680X	Lock (door)—front R. H. and rear L. H.	1913-21	40
5679X	Lock (door)—rear R. H.	1913-21	40
7128X	Panel (front door)	1915-21	1 25
8449AX	Panel (front seat back) and trim rail assy.	1915-21	4 25
8449BX	Panel (front seat back) and trim rail assy.	1921-23	4 25
5123AX	Panel (front side) R. H.	1915-21	4 25
5123BX	Panel (front side) R. H.	1921-21	3 00
5122AX	Panel (front side) L. H.	1915-21	4 25
5122BX	Panel (front side) L. H.	1921-23	3 00
6602X	Panel (instrument board)	1919-21	1 00
7120X	Panel (rear door) R. H.	1915-21	1 25
7121X	Panel (rear door) L. H.	1915-21	1 25
7437X	Panel (rear seat back) and "T" moulding assy.	1921-23	4 00
8450X	Panel (rear seat back) and trim rail assy.	1915-21	10 50
7438X	Panel (rear side) and reinforcement assy.—R. H.	1921-23	3 50
7439X	Panel (rear side) and reinforcement assy.—L. H.	1921-23	3 50
8156AX	Panel (side) and frame assy.—R. H.	1915-21	*16 00
8156BX	Panel (side) and frame assy.—R. H.	1921-23	*20 00
8157AX	Panel (side) and frame assy.—L. H.	1915-21	*16 00
8157BX	Panel (side) and frame assy.—L. H.	1921-23	*20 00
7193AX	Pillar (dash) R. H.	1915-21	25
7193BX	Pillar (dash) R. H.	1921-23	25
7194AX	Pillar (dash) L. H.	1915-21	25
7194BX	Pillar (dash) L. H.	1921-23	25
7197AX	Pillar (front seat front) R. H.	1915-21	30
7197BX	Pillar (front seat front) R. H.	1921-23	50
7198AX	Pillar (front seat front) L. H.	1951-21	30
7198BX	Pillar (front seat front) L. H.	1921-23	50
7200AX	Pillar (front seat rear) R. H.	1915-21	35
7200BX	Pillar (front seat rear) R. H.	1921-23	50
7201AX	Pillar (front seat rear) L. H.	1915-21	35
7201BX	Pillar (front seat rear) L. H.	1921-23	50
7195AX	Pillar (panel) R. H.	1915-21	40
7195BX	Pillar (panel) R. H.	1921-23	40
7196AX	Pillar (panel) L. H.	1915-21	40
7196BX	Pillar (panel) L. H.	1921-23	40
7202AX	Pillar (rear seat) R. H.	1915-21	60
7202BX	Pillar (rear seat) R. H.	1921-23	80
7203AX	Pillar (rear seat) L. H.	1915-21	60
7203BX	Pillar (rear seat) L. H.	1921-23	80

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.



Part No.	NAME	YEAR	Tax PRICE Status
----------	------	------	------------------


### TOURING CAR BODY PARTS—Continued

5205X	Pin (door hinge) side	1912-21	\$ 0 01
8433X	Plate (lock striker)	1917-21	10
7216X	Rail (front seat trim) assy.	1915-21	1 00
8398BX	Rail (front seat trim) center	1921-23	50
8399BX	Rail (front seat trim) side—front—R. H.	1921-23	20
7390X	Rail (front seat trim) side—front—L. H.	1921-23	25
7387X	Rail (front seat trim) side—intermediate—R. H.	1921-23	35
7389X	Rail (front seat trim) side—intermediate—L. H.	1921-23	35
7391X	Rail (front seat trim) side—rear—R. H.	1921-23	35
7392X	Rail (front seat trim) side—rear—L. H.	1921-23	35
7204AX	Rail (front top) R. H.	1915-21	35
7204BX	Rail (front top) R. H.	1921-23	35
7205AX	Rail (front top) L. H.	1915-21	35
7205BX	Rail (front top) L. H.	1921-23	35
7240X	Rail (rear seat trim) assy.	1915-21	1 00
8371BX	Rail (rear seat trim) center	1921-23	25
8381X	Rail (rear seat trim) side—R. H.	1921-23	75
8397X	Rail (rear seat trim) side—L. H.	1921-23	40
7206X	Rail (side top) R. H.	1915-23	20
7207AX	Rail (side top) L. H.	1915-21	30
7207BX	Rail (side top) L. H.	1921-23	30
7291BX	Riser (front floor board) R. H.	1921-23	20
7292BX	Riser (front floor board) L. H.	1921-23	20
8460X	Sill (rear end)	1915-17 and 20-21	90
7135BX	Sill (rear end)	1921-23	45
7175AX	Sill (side) assy.—R. H.	1915-21	3 25
7175BX	Sill (side) assy.—R. H.	1921-23	3 50
7176AX	Sill (side) assy.—L. H.	1915-21	3 25
7176BX	Sill (side) assy.—L. H.	1921-23	3 50
8151AX	Spring (front back)	1916-21	1 25
8151BX	Spring (front back)	1921-23	1 25
8063AX	Spring (front cushion)	1915-21	2 00
8063BX	Spring (front cushion)	1921-23	2 00
8152AX	Spring (rear back)	1916-21	1 25
8152BX	Spring (rear back)	1921-23	1 25
5670AX	Spring (rear cushion)	1915-21	2 25
5670BX	Spring (rear cushion)	1921-23	2 25
7208AX	Strainer (blind side)	1915-21	10
7208BX	Strainer (blind side)	1921-23	10
7135X	Strainer (rear seat)	1915-21	35
5454X	Strap (door)	1913-21	10
5682AX	Support (floor board) rear	1914-21	15
5683BX	Support (floor board) rear	1921-23	10
7153X	Support (trim rail)	1915-21	15
8083X	Upholstering (blind door) assy.	1915-23	40
8084X	Upholstering (front) assy.	1915-23	15
8075X	Upholstering (front door) assy.	1915-23	30
8077AX	Upholstering (front seat back) assy.	1915-21	4 50
8077BX	Upholstering (front seat back) assy.	1921-23	4 00
8376X	Upholstering (rear door) assy.—R. H.	1915-21	40
8377X	Upholstering (rear door) assy.—L. H.	1915-21	40
8078AX	Upholstering (rear seat back) assy.	1915-21	5 00
8078BX	Upholstering (rear seat back) assy.	1921-23	5 00

### COUPE AND SEDAN WINDSHIELD

9025X	Bolt (glass clip)—Cp. Sn.	1915-23	05
8689X	Bracket (hinge) on pillar—Cp. Sn.	1916-23	40
9530X	Bracket (hinge) assy.—on pillar—R. H.—Cp. Sn.	1915-19	1 00
9531X	Bracket (hinge) assy.—on pillar—L. H.—Cp. Sn.	1915-19	1 00
9532X	Bracket (hinge) on sash—R. H.—Cp. Sn.	1916-19	1 00
9533X	Bracket (hinge) on sash—L. H.—Cp. Sn.	1916-19	1 00
9000X	Bracket (ventilating) assy.—on pillar—R. H.—Cp. Sn.	1915-19	1 00
9001X	Bracket (ventilating) assy.—on pillar—L. H.—Cp. Sn.	1915-19	1 00
9004X	Bracket (ventilating) on pillar—R. H.—Cp. Sn.	1915-19	90
9046X	Bracket (ventilating) on pillar—R. H.—(Cp. 1919-23) Sn.	1915-23	30
9005X	Bracket (ventilating) on pillar—L. H.—Cp. Sn.	1915-19	90
9047X	Bracket (ventilating) on pillar—L. H.—(Cp. 1919-23) Sn.	1915-23	30
9002X	Bracket (ventilating) on sash—R. H.—Cp. Sn.	1915-23	15
9003X	Bracket (ventilating) on sash—L. H.—Cp. Sn.	1915-23	15
9066X	Channel (center)—rubber—Cp. Sn.	1915-23	35
9013X	Clip (glass) lower—Cp. Sn.	1915-23	10
9011X	Clip (upper glass) R. H.—Cp. Sn.	1915-23	10
9012X	Clip (upper glass) L. H.—Cp. Sn.	1915-23	10
9021X	Cone (hinge friction) Cp. Sn.	1915-19	15
6880X	Glass (upper and lower) 37 1/4" x 9 3/4"—Cp. Sn.	1916-19	
9534X	Glass (upper and lower) 37 1/4" x 9 3/4"—(Cp. 1919-23) Sn.	1916-23	

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.




Note — Where marked R, H there is always a left hand of like same piece or vice versa

Part No.	NAME	YEAR	PRICE	Tax Status
<b>COUPE AND SEDAN WINDSHIELD—Continued</b>				
9014AX	Handle (lower sash) Cp. Sn.	1915-20		\$ 0 20
9014BX	Handle (lower sash) Cp. Sn.	1920-23		10
9528AX	Hinge (upper) assy.—R. H.—Cp. Sn.	1916-20		2 00
9528BX	Hinge (upper) assy.—R. H.—Cp. Sn.	1920-23		2 25
9529AX	Hinge (upper) assy.—L. H.—Cp. Sn.	1916-20		2 00
9529BX	Hinge (upper) assy.—L. H.—Cp. Sn.	1920-23		2 25
9026X	Nut (glass clip) Cp. Sn.	1915-23		50
9090X	Retainer (glass) (Cp. 1920-22) Sn.	1915-23		10
9027X	Retainer (glass) side—Cp.	1915-19		30
9028X	Retainer (glass) upper and lower—Cp.	1916-19		15
9573X	Retainer (weather strip) side—Cp.	1916-20		15
9537X	Retainer (weather strip) side—(Cp. 1919-21) Sn.	1920-21		20
5364X	Retainer (weather strip) side—R. H.—Sn.	1922-23		50
10695BX	Retainer (weather strip) side—L. H.—Sn.	1920-21		20
5365X	Retainer (weather strip) side—L. H.	1922-23		50
10696BX	Retainer (weather strip) upper—Cp.	1916-19		20
9572X	Retainer (weather strip) upper—(Cp. 1919-22) Sn.	1916-21		20
9536X	Sash (lower) Cp.	1916-19		7 50
9545X	Sash (lower) (Cp. 1919-22) Sn.	1916-23		6 50
9544X	Sash (upper) Cp.	1916-19		7 50
9526BX	Sash (upper) Cp. Sn.	1920-23		6 50
9526AX	Sash (upper) Sn.	1916-19		7 50
9222X	Screw (lower sash handle)	1920-23		03
9574AX	Screw (upper hinge clamp) Cp. Sn.	1916-19		35
9574BX	Screw (upper hinge clamp) Cp. Sn.	1919-22		30
9022X	Screw (upper hinge friction cone) Cp. Sn.	1915-19		05
9006AX	Screw (ventilating bracket thumb) black—Cp. Sn.	1916-19		25
9006BX	Screw (ventilating bracket thumb) nickel—Cp. Sn.	1919-23		25
9645X	Strip (weather) side—rubber—Cp. Sn.	1916-23		10
9646X	Strip (weather) upper—rubber—Cp. Sn.	1916-23		20
9023X	Washer (hinge friction lock) Cp. Sn.	1915-19		01
9541X	Windshield complete—Cp.	1916-19		
9538X	Windshield complete—(Cp. 1919-23) Sn.	1916-23		
9543X	Windshield lower half assy.—Cp.	1916-19		
9525X	Windshield lower half assy.—(Cp. 1919-22) Sn.	1916-23		
9542X	Windshield upper half assy.—Cp.	1916-19		
9524BX	Windshield upper half assy.—Cp. Sn.	1919-23		12 00
9524AX	Windshield upper half assy.—Sn.	1916-19		12 00
<b>COUPE BODY PARTS</b>				
5052X	Anti-rattler (door) assembly—female	1922-23		30
5053X	Anti-rattler (door) assembly—male	1922-23		15
8320BX	Anti-rattler (door lock lever)	1920-23		05
9455X	Anti-rattler (door window) lower	1915-21		02
5095X	Anti-rattler (window lifter rod)	1922-23		03
5103X	Arm (window lifter counterbalance) assy.—R. H.	1922-23		40
5104X	Arm (window lifter counterbalance) assy.—L. H.	1922-23		40
10552X	Bar (door bottom) L. H.	1919-22		40
10551X	Bar (door bottom) R. H.	1919-22		40
9932AX	Beading (roof)	1919-21		3 00
9932BX	Beading (roof) front	1922-23		60
9346X	Beading (roof) rear	1922-23		75
10549AX	Board (door bottom) R. H.	1919-22		75
10549BX	Board (door bottom) R. H.	1922-23		75
10550AX	Board (door bottom) L. H.	1919-22		75
10550BX	Board (door bottom) L. H.	1922-23		75
10548X	Board (door garnish) L. H.	1919-23		60
10547X	Board (door garnish) R. H.	1919-23		60
10547BX	Board (door lock) R. H.	1922-23		65
10545AX	Board (door lock) R. H.	1919-22		65
10546AX	Board (door lock) L. H.	1919-22		65
10546BX	Board (door lock) L. H.	1922-23		65
10646X	Board (floor) No. 4	1919-23		40
10648AX	Board (instrument)	1919-21		1 00
10648BX	Board (instrument)	1922-23		1 00
10528X	Board (quarter garnish) R. H.	1919-22		75
10529X	Board (quarter garnish) L. H.	1919-22		75
9700X	Bolt (det. pillar lock clamp)	1917-19		25
9458X	Brace (coupe pillar) R. H.	1915-20		25
9459X	Brace (coupe pillar) L. H.	1915-20		25
9105X	Bracket (hand rail)	1915-21		10
9486X	Bumper (deck door)	1916-23		05
6927AX	Bumper (door)	1915-21		05
6927BX	Bumper (door)	1922-23		05
9211RX	Bumper (door sill plate)	1919-21		05
6932RX	Bumper (door top rail)	1915-21		05
10728BX	Carpet (cowl upholstery) assy.—R. H.	1919-23		1 25

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.







Part No.	NAME	YEAR	Tax PRICE Status
<b>COUPE BODY PARTS—Continued</b>			
10570X	Pillar (deck) rear—R. H.	1919-23	\$ 0 65
10571X	Pillar (deck) rear—L. H.	1919-23	65
9943X	Pillar (det. top lock) assy.—R. H.	1918	10 50
9944X	Pillar (det. top lock) assy.—L. H.	1918	10 50
10516ARX	Pillar (hinge) R. H.	1919-21	3 00
10516BX	Pillar (hinge) R. H.	1922	3 00
10517CX	Pillar (hinge) R. H.	1922-23	3 45
10517ARX	Pillar (hinge) L. H.	1919-21	3 00
10517BX	Pillar (hinge) L. H.	1922	3 00
10517CX	Pillar (hinge) L. H.	1922-23	3 45
10540AX	Pillar (hinge) on door—R. H.	1919-21	2 75
10540BX	Pillar (hinge) on door—R. H.	1922	2 00
10540CX	Pillar (hinge) on door—R. H.	1922-23	2 70
10541AX	Pillar (hinge) on door—L. H.	1919-21	2 75
10541BX	Pillar (hinge) on door—L. H.	1922	2 00
10541CX	Pillar (hinge) on door—L. H.	1922-23	2 70
10538AX	Pillar (lock) R. H.	1919-21	2 75
10539AX	Pillar (lock) L. H.	1919-21	2 75
10538BX	Pillar (lock) R. H.	1922	2 25
10538CX	Pillar (lock) R. H.	1922-23	2 65
10539BX	Pillar (lock) R. H.	1922	2 25
10539CX	Pillar (lock) R. H.	1922-23	2 65
9965X	Pillar (quarter) R. H.	1918-19	5 00
10518ARX	Pillar (quarter) R. H.	1919-21	2 25
10518BX	Pillar (quarter) R. H.	1922	1 75
10518CX	Pillar (quarter) R. H.	1922-23	2 20
9966X	Pillar (quarter) L. H.	1918-19	5 00
10519ARX	Pillar (quarter) L. H.	1919-21	2 25
10519BX	Pillar (quarter) L. H.	1922	1 75
10519CX	Pillar (quarter) R. H.	1922-23	2 20
10587X	Pillar (quarter panel) R. H.	1919-23	80
10588X	Pillar (quarter panel) L. H.	1919-23	80
9654X	Pin (door hinge)	1915-23	03
9479X	Pin (window lifter)	1915-23	03
9487X	Plate (deck door bumper)	1916-23	05
9485X	Plate (deck door lock striker)	1916-23	03
5059X	Plate (door anti-rattler cushion)	1922-23	03
9741X	Plate (door lever handle)	1918-19	15
9058X	Plate (door lock lever) R. H.	1915-18	15
9056X	Plate (door lock lever) L. H.	1915-18	15
9060X	Plate (door lock striker)	1919-23	10
9106X	Plate (door sill) R. H.	1915-18	75
9727X	Plate (door sill) R. H.	1919-23	30
9107X	Plate (door sill) L. H.	1915-18	75
9728X	Plate (door sill) L. H.	1919-23	30
5088X	Plate (window lifter spring suspension)	1922-23	05
9073X	Plate (window lifter strap)	1915-21	03
9470X	Plunger (door dove-tail)	1918-19	40
7590X	Plunger (door lock) R. H.	1915-23	20
9454X	Plunger (door lock) L. H.	1915-23	20
9948X	Post (body hinge) R. H.	1917-19	7 00
9950X	Post (body hinge) L. H.	1917-19	7 00
5224X	Rack door window lifter—R. H.	1922-23	50
5225X	Rack door window lifter—L. H.	1922-23	50
10575X	Rail (deck) R. H.	1919-23	60
10576X	Rail (deck) L. H.	1919-23	60
10577X	Rail (deck) rear	1919-23	60
10542X	Rail (door belt)	1919-23	1 50
9822X	Rail (door hand) assy.	1916-21	1 00
10531X	Rail (front belt)	1919-23	1 25
10523X	Rail (lower back panel) bottom	1919-23	70
10530X	Rail (quarter belt)	1919-23	90
10532X	Rail (rear belt) assy.	1919-23	3 00
10556ARX	Rail (roof) assy.—rear	1917-21	4 50
10556BX	Rail (roof) assy.—rear	1922-23	4 50
10553ARX	Rail (roof) front	1917-21	2 00
10553BX	Rail (roof) front	1922-23	2 00
9761X	Rail (roof) side—R. H.	1917-19	7 50
10554ARX	Rail (roof) side—R. H.	1920-21	4 00
10554BX	Rail (roof) side—L. H.	1922-23	4 00
9762X	Rail (roof) side—L. H.	1917-19	7 50
10555ARX	Rail (roof) side—L. H.	1920-21	4 00
10555BX	Rail (roof) side—L. H.	1922-23	4 00
10611X	Reinforcement (coupe pillar) R. H.	1919-23	20
10612X	Reinforcement (coupe pillar) L. H.	1919-23	20
5238X	Retainer (door window weather strip)	1922-23	15
9140X	Retainer (seat cushion)	1915-21	50
10560BX	Rib (roof) No. 1	1919-23	50
10561BX	Rib (roof) No. 2	1919-23	50
10562BX	Rib (roof) No. 3	1919-23	50

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

Part No.	NAME	YEAR	PRICE	Tax Status
<b>COUPE BODY PARTS—Continued</b>				
10563BX	Rib (roof) No. 4	1919-23	\$ 0 50	
10662X	Riser (front floor board) assy.—R. H.	1919-23	60	
10663X	Riser (front floor board) assy.—L. H.	1919-23	60	
10604AX	Riser (seat) front	1919-21	1 75	
10604BX	Riser (seat) front	1922-23	1 75	
10605X	Riser (seat) rear	1919-23	1 00	
10613X	Rocker—R. H.	1919-23	1 25	
10614X	Rocker—L. H.	1919-23	1 25	
5081X	Rod (window lifter) assy.—R. H.	1922-23	60	
5082X	Rod (window lifter) assy.—L. H.	1922-23	60	
9759A1X	Roller (window curtain) assy.	1922-23	1 25	
5066A1X	Run (door window glass)—felt	1922-23	75	
5066A1X	Run (quarter window glass)—felt	1922-23	75	
5066A2X	Run (window glass)—rubber	1922-23	50	
5066A2X	Run (window glass)—rubber	1922-23	50	
1473X	Screw (dash lamp bracket)	1915-19	02	
10619X	Sill (cross) rear	1919-23	60	
10665X	Sill (side) assy.—R. H.	1919-23	10 00	
10666X	Sill (side) assy.—L. H.	1919-23	10 00	
9475X	Socket (door dove-tail)	1915-19	15	
9938X	Spring (back cushion)	1915-23	2 00	
9183X	Spring (door lock lever)	1915-23	05	
8122BX	Spring (seat cushion)	1915-23	4 00	
5092X	Spring (window lifter counterbalance)	1922-23	15	
5067BX	Spring (window lifter rod)	1922-23	03	
10631X	Strainer (back) lower	1919-23	25	
10681X	Strainer (back) upper	1919-23	15	
10582X	Strainer (deck rear)	1919-23	35	
10580X	Strainer (deck side) R. H.	1919-23	25	
10581X	Strainer (deck side) L. H.	1919-23	25	
9059AX	Strap (door check) assy.	1915-21	40	
9059BX	Strap (door check) assy.	1922-23	40	
10735AX	Strip (back window finish) assy.	1919-21	1 25	
10735BX	Strip (back window finish) assy.	1922-23	1 25	
9713X	Strip (deck opening finish)	1916-23	1 00	
9467X	Strip (door garnish finish) R. H.	1916-23	90	
8649AX	Strip (door garnish finish) R. H.	1915-19	90	
8649BX	Strip (door garnish finish) R. H.	1919-20	25	
8649CX	Strip (door garnish finish) R. H.	1920-21	25	
9468X	Strip (door garnish finish) L. H.	1916-19	90	
8679AX	Strip (door garnish finish) L. H.	1915-19	90	
8679BX	Strip (door garnish finish) L. H.	1919-20	25	
8679CX	Strip (door garnish finish) L. H.	1920-21	25	
10504X	Strip (door header finish) R. H.	1919-21	35	
10505X	Strip (door header finish) L. H.	1919-21	35	
10506X	Strip (door hinge pillar finish) R. H.	1919-21	25	
10501X	Strip (door hinge pillar finish) L. H.	1919-21	25	
5245X	Strip (door lock pillar finish)	1922-23	30	
10752AX	Strip (door window glass retainer) $\frac{1}{8}$ " thick	1922-23	15	
10752BX	Strip (door window glass retainer) $\frac{1}{8}$ " thick	1922-23	15	
5233X	Strip (door window weather)	1922-23	15	
5246X	Strip (hinge pillar finish)	1922-23	30	
9929X	Strip (hinge pillar finish) R. H.	1917-19	25	
10508X	Strip (hinge pillar finish) R. H.	1919-21	25	
9098X	Strip (hinge pillar finish) L. H.	1917-19	25	
10509X	Strip (hinge pillar finish) L. H.	1919-21	25	
10502X	Strip (lock pillar finish) R. H.	1919-21	20	
10503X	Strip (lock pillar finish) L. H.	1919-21	20	
9941X	Strip (quarter garnish finish)	1917-19	25	
10506BX	Strip (quarter garnish finish)	1919-21	25	
10506CX	Strip (quarter garnish finish)	1922-23	30	
10512X	Strip (quarter header finish) R. H.	1919-21	15	
10513X	Strip (quarter header finish) L. H.	1919-21	15	
5246X	Strip (quarter pillar finish)	1922-23	30	
10510X	Strip (quarter pillar finish) R. H.	1919-21	25	
10511X	Strip (quarter pillar finish) L. H.	1919-21	25	
8679DX	Strip (door garnish finish) L. H.—with pull bars	1922-23	25	
8679EX	Strip (door garnish finish) R. H.—with pull bars	1922-23	25	
8649DX	Strip (door garnish finish) R. H.—with pull bars	1922-23	25	
8649EX	Strip (door garnish finish) R. H.—with pull bars	1923	35	
10754AX	Strip (quarter window glass retainer) $\frac{1}{8}$ " thick	1922-23	15	
10754BX	Strip (quarter window glass retainer) $\frac{1}{8}$ " thick	1922-23	15	
9617X	Strip (roof drip moulding finish)	1922-23	20	
9488X	Support (deck door)	1916-23	25	
10736BX	Trimming (door weather strip) assy.	1922-23	40	
10736CX	Trimming (door weather strip) assy.	1923	40	
10733X	Trimming (heel board)	1919-21	50	
8518X	Upholstering (cowl) assy.—R. H.	1915-19	1 00	
8519X	Upholstering (cowl) assy.—L. H.	1915-19	1 00	
8520X	Upholstering (cowl) upper	1915-19	2 00	

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/2 represents excise tax.

Part No.	NAME	YEAR	PRICE	Tax Status
<b>COUPE BODY PARTS—Continued</b>				
9902AX	Upholstering (door) assy.—R. H.	1918-21	\$ 7 00	
9903AX	Upholstering (door) assy.—L. H.	1918-21	7 00	
9902BX	Upholstering (door) assy.—R. H.	1922-23	4 50	
9902CX	Upholstering (door) assy.—R. H.	1923	4 50	
9903BX	Upholstering (door) assy.—L. H.	1922-23	4 50	
9903CX	Upholstering (door) assy.—L. H.	1923	4 50	
9896BX	Upholstering (quarter) assy.—R. H.	1919-21	2 25	
9896CX	Upholstering (quarter) assy.—R. H.	1922-23	2 50	
9896DX	Upholstering (quarter) assy.—R. H.	1923	2 50	
9897BX	Upholstering (quarter) assy.—L. H.	1919-21	2 25	
9897CX	Upholstering (quarter) assy.—L. H.	1922-23	2 50	
9897DX	Upholstering (quarter) assy.—L. H.	1923	2 50	
9921X	Upholstering (seat back) assy.	1918-19	12 00	
10451AX	Upholstering (seat back) assy.	1919-21	6 50	
10451BX	Upholstering (seat back) assy.	1922-23	7 50	
10451CX	Upholstering (seat back) assy.	1923	7 50	
10450AX	Upholstering (seat cushion) assy.	1919-21	6 00	
10450BX	Upholstering (seat cushion) assy.	1922-23	9 00	
10450CX	Upholstering (seat cushion) assy.	1923	9 00	
5068X	Washer (window lifter rod)	1922	01	
19883X	Window (door) R. H.	1918-19	12 00	
18379X	Window (door) R. H.	1919-21	6 50	
19884X	Window (door) L. H.	1918-19	12 00	
18402X	Window (door) L. H.	1919-21	8 50	
18415X	Window (quarter)	1919-21	6 50	
19894X	Window (quarter) R. H.	1918-19	10 50	
19895X	Window (quarter) L. H.	1918-19	10 50	
<b>SEDAN BODY PARTS</b>				
5052X	Anti-rattler (door) assy.—female	1922-23	30	
5053X	Anti-rattler (door) assy.—male	1922-23	15	
8320AX	Anti-rattler (door lock lever)	1919-20	05	
8320BX	Anti-rattler (door lock lever)	1921-23	05	
9455X	Anti-rattler (window)	1916-21	02	
5095X	Anti-rattler (window lifter rod)	1922-23	03	
5104X	Arm (door window lifter) assy.—R. H.	1922-23	40	
5103X	Arm (door window lifter) assy.—L. H.	1922-23	40	
5103X	Arm (front quarter window lifter) assy.—R. H.	1922-23	40	
5104X	Arm (front quarter window lifter) assy.—L. H.	1922-23	40	
9681CRX	Back (driver's seat) assy.—with uphol.—malleable	1922	10 00	
9681DRX	Back (driver's seat) assy.—with uphol.—pressed steel	1922-23	10 00	
9681ERX	Back (driver's seat) assy.—with uphol.—pressed steel	1923	10 00	
9668ARX	Back (pass. seat) assy.—less uphol.—malleable	1917-20	3 75	
9679ARX	Back (pass. seat) assy.—with uphol.	1917-20	10 00	
9679CRX	Back (pass. seat) assy.—with uphol.—less supports—malleable	1922	9 50	
9679DRX	Back (pass. seat) assy.—with uphol.—less supports—pressed steel	1922-23	9 50	
9679ERX	Back (pass. seat) assy.—with uphol.—less supports—pressed steel	1923	9 50	
10029X	Bar (door bottom) R. H.	1919-23	80	
10030X	Bar (door bottom) L. H.	1919-23	80	
9825X	Base (driver's seat)	1916-23	2 00	M H
10106X	Block (cowl reinforcement)	1916-23	10	
10107X	Board (door bottom)	1919-23	50	
8162X	Board (floor) 1st	1916-23	70	M H
8163X	Board (floor) 2nd	1916-23	70	M H
8164X	Board (floor) 3rd—lower	1916-23	90	M H
8164X	Board (floor) 3rd—upper	1916-23	45	M H
9495X	Board (floor) assy.—1st	1916-23	1 00	M H
9496X	Board (floor) assy.—2nd	1916-23	1 00	M H
8169X	Board (floor) assy.—3rd	1916-23	1 70	M H
10134ARX	Board (instrument)	1919-22	1 25	
10134BX	Board (instrument)	1922-23	1 00	
10037X	Board (lock) R. H.	1919-23	50	
10038X	Board (lock) L. H.	1919-23	50	
10135AX	Bottom (pass. seat)—for malleable back	1922	1 00	
10135CX	Bottom (pass. seat)—for pressed steel back	1922-23	1 00	
9553X	Brace (body hinge pillar) R. H.	1922-23	20	
9554X	Brace (body hinge pillar) L. H.	1922-23	20	
9500X	Brace (body lock pillar)	1916-23	25	
9498X	Brace (coupe pillar) R. H.	1916-23	25	
9499X	Brace (coupe pillar) L. H.	1916-23	25	
9502X	Brace (rear pillar) R. H.	1916-23	40	
9503X	Brace (rear pillar) L. H.	1916-23	40	
9846BX	Bracket (curtain roller) notched—Fisher design	1915-23	30	
9846AX	Bracket (curtain roller) notched—Ford design	1915-23	30	
Window lifter not included.				
Four-door sedan cloth.				

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.




Part No.	NAME	YEAR	PRICE	Tax Status
<b>SEDAN BODY PARTS—Continued</b>				
5397BX	Cover (front belt rail)	1922-23	\$ 0 45	
5406X	Cover (front quarter belt rail) R. H.	1922-23	40	
5407X	Cover (front quarter belt rail) L. H.	1922-23	40	
5410X	Cover (front quarter header) R. H.	1922-23	60	
5411X	Cover (front quarter header) L. H.	1922-23	60	
5421X	Cover (rear quarter belt rail) inside—R. H.	1922-23	15	
5422X	Cover (rear quarter belt rail) inside—L. H.	1922-23	15	
5408X	Cover (rear quarter belt rail) outside—R. H.	1922-23	60	
5409X	Cover (rear quarter belt rail) outside—L. H.	1922-23	60	
5412X	Cover (rear quarter header) R. H.	1922-23	60	
5413X	Cover (rear quarter header) L. H.	1922-23	60	
5414X	Cover (rear quarter pillar) R. H.	1922-23	60	
5415X	Cover (rear quarter pillar) L. H.	1922-23	60	
5416X	Cover (roof rail—front)	1922-23	40	
5404X	Cover (windshield header)	1922-23	50	
9283X	Cowl	1915-23	7 00	
10366AX	Curtain (rear window) assy.	1915-23	3 00	
5057X	Cushion (door) anti-rattler	1922-23	05	
9680AX	Cushion (driver's seat) assy.	1917-21	6 00 M H	
9680BX	Cushion (driver's seat) assy.	1922-23	8 00 M H	
9680CX	Cushion (driver's seat) assy.	1923	8 00 M H	
9682X	Cushion (rear seat) assy.	1916-19	*16 00 M H	
9621BX	Cushion (rear seat) assy.	1920-21	*13 00 M H	
9621CX	Cushion (rear seat) assy.	1922-23	*15 00 M H	
9621DX	Cushion (pass. seat) 1916-21—order 8124BX—Pass. seat cushion spring and 10456BX—pass. seat cushion upholstering assy.	1923	*15 00 M H	
	Cushion (pass. seat) 1922-23—order 8124BX—Pass. seat cushion spring and 10456CX Pass. seat cushion upholstering assy.			
	Cushion (pass. seat) 1923—order 8124BX—Pass. seat cushion spring and 10450DX Pass. seat cushion upholstering assy.			
10427AX	Cushion (rear seat back) assy.	1919-21	11 50	
10427BX	Cushion (rear seat back) assy.	1922-23	15 00	
10427CX	Cushion (rear seat back) assy.	1923	15 00	
2069AX	Cushion (steering column)	1920-23	05	
10074X	Door (battery trap)	1919-23	75	
9560AX	Door—less window—R. H.	1915-18	*45 00	
9560BX	Door—less window—R. H.	1919-21	*35 00	
9560CX	Door—with window—R. H.	1922-23	*35 00 M H	
9561AX	Door—less window—L. H.	1915-18	*45 00	
9561BX	Door—with window—L. H.	1919-21	*35 00	
9561CX	Door—with window—L. H.	1922-23	*35 00 M H	
9560DX	Door—with window—R. H.	1923	*35 00 M H	
5050X	Felt (rear quarter header)	1922-23	10	
9813X	Felt (window channel)	1915-21	30 yd	
9870X	Fence (door window) Wadsworth	1918-20	35	
9510AX	Fence (door window)	1916-21	35	
9510BX	Fence (door window)	1922-23	20	
9511X	Fence (front quarter window)	1916-21	35	
5098X	Fence (rear quarter window)	1922-23	20	
9510X	Fence (rear quarter window)	1916-21	35	
9870X	Fence (rear quarter window) Wadsworth	1918-20	35	
9084X	Fence (windshield)	1915-21	45	
9869X	Fence (windshield) Wadsworth	1918-19	45	
10155X	Frame (cowl) assy.	1916-23	2 00	
10161X	Frame (rear seat) assy.	1916-23	2 00	
10091X	Frame (rear window)	1916-23	2 00	
9257X	Glass (back window) 14 1/2" x 23 1/2" oval	1915-23	1 00	
9214AX	Glass (door window) 19 1/2" x 23 1/2"	1915-21		
9214BX	Glass (door window)	1922-23		
9563RX	Glass (door window) and channel assy.—R.	1922-23		
9564RX	Glass (door window) and channel assy.—L.	1922-23		
9513AX	Glass (front quarter window) 17 1/2" x 23 1/2"	1916-21		
9513BX	Glass (front quarter window)	1922-23		
9643RX	Glass (front quarter window) and channel assy.—R.	1922-23		
9644RX	Glass (front quarter window) and channel assy.—L.	1922-23		
9514AX	Glass (rear quarter window) 19 1/2" x 23 1/2"	1916-21		
9514BX	Glass (rear quarter window)	1922-23		
9058DX	Grip (door lock) and ferrule assy.—"L"	1922-23	75	
9058AX	Grip (door lock) and ferrule assy.—loop—black	1915-18	1 50	
9058BX	Grip (door lock) and ferrule assy.—loop—nickel	1919-20	1 50	
9058CX	Grip (door lock) and ferrule assy.—"T"	1921	50	
5378X	Handle (door pull)	1922-23	75	
10059AX	Header (door) R. H.—specify make of body	1915-21	1 50	
10059BX	Header (door) R. H.	1922-23	60	
10060AX	Header (door) L. H.—specify make of body	1915-21	1 50	
10060BX	Header (door) L. H.	1922-23	60	

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

Part No.	NAME	YEAR	PRICE	Tax Status
<b>SEDAN BODY PARTS—Continued</b>				
10062AX	Header (front quarter) R. H.—specify make of body	1915-21	\$ 2 00	
10062BX	Header (front quarter) R. H.	1922-23	60	
10063AX	Header (front quarter) L. H.—specify make of body	1915-21	2 00	
10063BX	Header (front quarter) L. H.	1922-23	60	
10056AX	Header (rear quarter) R. H.—specify make of body	1915-21	2 00	
10056BX	Header (rear quarter) R. H.	1922-23	60	
10057AX	Header (rear quarter) L. H.—specify make of body	1915-21	2 00	
10057BX	Header (rear quarter) L. H.	1922-23	60	
10025AX	Header (windshield)	1915-21	2 00	
10025BX	Header (windshield)	1922-23	70	
9204X	Hinge (center) assy.	1915-23	50	
9206X	Hinge (lower) assy.	1915-23	50	
9202X	Hinge (upper) assy.	1915-23	50	
10403X	Lace (pasting) and seaming cord assy.—specify year	1915-21	10 yd	
10342BX	Lace (pasting)	1922-23	15 yd	
9664AX	Leg (pass. seat front) assy.—R. H.	1917-19	1 00	
9664BX	Leg (pass. seat front) assy.—R. H.	1919-23	1 00 M H	
9665AX	Leg (pass. seat front) assy.—L. H.	1917-19	1 00	
9665BX	Leg (pass. seat front) assy.—L. H.	1919-23	1 00 M H	
9780BX	Leg (pass. seat front) lower	1917-23	50 M H	
9781BX	Leg (pass. seat front) upper—R. H.	1916-23	50 M H	
9782BX	Leg (pass. seat front) upper—L. H.	1916-23	50 M H	
9620X	Leg (pass. seat rear) assy.	1917-20	75 M H	
9666AX	Leg (pass. seat rear) lower	1917-19	50	
9666BX	Leg (pass. seat rear) lower	1919-23	50 M H	
8822A	Leg (pass. seat rear) upper	1919-23	25	
9608X	Lifter (door window)	1915-20	1 25	
9606AX	Lifter (quarter window)	1915-20	65	
9606BX	Lifter (rear quarter window)	1922-23	75	
9606CX	Lifter (rear quarter window)	1923	75	
9606X	Lifter (window)	1920-21	65	
9540AX	Lining (head) assy.	1915-21	4 00	
9540BX	Lining (head) assy.	1922-23	8 50	
9540CX	Lining (head) assy.	1923	8 50	
9052AX	Lock (door) assy.—R. H.	1915-19	1 25	
9052BX	Lock (door) assy.—R. H.	1919-23	1 25	
9051AX	Lock (door) assy.—L. H.	1915-19	1 25	
9051BX	Lock (door) assy.—L. H.	1919-23	1 25	
10281X	Moulding (belt) door	1916-23	90	
10282X	Moulding (belt) front	1916-23	3 00	
10288X	Moulding (cowl) R. H.	1916-23	50	
10289X	Moulding (cowl) L. H.	1916-23	50	
10294AX	Moulding (door hinge pillar "T") intermediate—R. H.	1916-21	30	
10294BX	Moulding (door hinge pillar "T") intermediate—R. H.	1922-23	30	
10295AX	Moulding (door hinge pillar "T") intermediate—L. H.	1916-21	30	
10295BX	Moulding (door hinge pillar "T") intermediate—L. H.	1922-23	30	
10296X	Moulding (door hinge pillar "T") lower—R. H.	1916-23	25	
10297X	Moulding (door hinge pillar "T") lower—L. H.	1916-23	25	
10292X	Moulding (door hinge pillar "T") upper—R. H.	1916-23	20	
10293X	Moulding (door hinge pillar "T") upper—L. H.	1916-23	20	
10298X	Moulding (door lock pillar and bottom "T") R. H.	1916-23	70	
10299X	Moulding (door lock pillar and bottom "T") L. H.	1916-23	70	
10287X	Moulding (rear belt)	1916-23	1 25	
10283X	Moulding (rear quarter belt) R. H.	1916-23	1 00	
10284X	Moulding (rear quarter belt) L. H.	1916-23	1 00	
10285X	Moulding (rear quarter) upper—R. H.	1916-23	50	
10286X	Moulding (rear quarter) upper—L. H.	1916-23	50	
9297AX	Moulding (roof drip)	1915-21	3 00	
9297BX	Moulding (roof drip) side	1922-23	60	
10290X	Moulding (roof) front	1922-23	50	
5085X	Nut (window lifter rod)	1922-23	03	
8516X	Panel (back lower) assy.—includes rear quarter panels—specify year and make of body	1916-23	*25 00	
9570X	Panel (back upper)—specify year and make of body	1916-23	12 00	
9567AX	Panel (door) R. H.—specify year	1915-21	3 50	
9567DX	Panel (door) R. H.	1922-23	3 50	
9568AX	Panel (door) L. H.—specify year	1915-21	3 50	
9568DX	Panel (door) L. H.	1922-23	3 50	
9569X	Panel (front quarter) R. H.	1915-23	8 50	
9565X	Panel (front quarter) L. H.	1915-23	8 50	
8025AX	Panel (instrument board)	1919-21	1 50	
8025BX	Panel (instrument board)	1922-23	1 25	
9876X	Panel (rear quarter) assy.—R. H.—specify make of body	1915-23	8 50	
9882X	Panel (rear quarter) assy.—L. H.—specify make of body	1915-23	8 50	

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.



Part No.	NAME	YEAR	Tax PRICE Status
----------	------	------	------------------

### SEDAN BODY PARTS—Continued

9074X	Panel (roof)	1915-23	\$15 00
9818X	Panel (sill)	1916-23	25
10003X	Pillar (body hinge) assy.—R. H.—specify make of body	1915-21	4 50
11020X	Pillar (body hinge) assy.—R. H.	1922-23	2 25
10004X	Pillar (body hinge) assy.—L. H.—specify make of body	1915-21	4 50
11021X	Pillar (body hinge) assy.—L. H.	1922-23	2 25
10005X	Pillar (body lock) assy.—R. H.—specify make of body	1915-21	10 00
11022X	Pillar (body lock) assy.—R. H.	1922-23	3 50
10010X	Pillar (body lock) assy.—L. H.—specify make of body	1915-21	10 00
11023X	Pillar (body lock) assy.—L. H.	1922-23	3 50
11018X	Pillar (coupe) assy.—R. H.	1922-23	4 50
10001X	Pillar (coupe) R. H.—specify make of body	1915-21	8 00
11019X	Pillar (coupe) assy.—L. H.	1922-23	4 50
10002X	Pillar (coupe) L. H.—specify make of body	1915-21	8 00
10005AX	Pillar (door hinge) R. H.—specify make of body	1915-21	6 00
10005BX	Pillar (door hinge) R. H.	1922-23	2 25
10006AX	Pillar (door hinge) L. H.—specify make of body	1915-21	6 00
10006BX	Pillar (door hinge) L. H.	1922-23	2 25
10007AX	Pillar (door lock) R. H.—specify make of body	1915-21	6 00
10007BX	Pillar (door lock) R. H.	1922-23	2 25
10008AX	Pillar (door lock) L. H.—specify make of body	1915-21	6 00
10008BX	Pillar (door lock) L. H.	1922-23	2 25
10011AX	Pillar (quarter) R. H.—specify make of body	1915-21	5 00
10011BX	Pillar (quarter) R. H.	1922-23	2 25
10012AX	Pillar (quarter) L. H.—specify make of body	1915-21	5 00
10012BX	Pillar (quarter) L. H.	1922-23	2 25
5059X	Plate (door anti-rattler)	1922-23	03
9060X	Plate (door lock striker)	1915-23	10
9208X	Plate (door sill) R. H.	1915-23	40
9209X	Plate (door sill) L. H.	1915-23	40
7667X	Plate (steering column)	1919-23	10
5088X	Plate (window lifter spring suspension)	1922-23	05
5079X	Rack (door window lifter—R. H.)	1922-23	50
5080X	Rack (door window lifter—L. H.)	1922-23	50
5078X	Rack (front quarter window lifter)	1922-23	50
10069AX	Rail (door belt)	1915-21	1 25
10069BX	Rail (door belt) R. H.	1922-23	50
10078X	Rail (door belt) L. H.	1922-23	50
9822X	Rail (door hand) assy.	1915-21	1 00
10023BX	Rail (front belt)	1922-23	60
10143X	Rail (front belt) and instrument board assy.	1915-21	3 25
10067AX	Rail (front quarter belt) R. H.	1915-21	1 00
10067BX	Rail (front quarter belt) R. H.	1922-23	60
10068AX	Rail (front quarter belt) L. H.	1915-21	1 00
10068BX	Rail (front quarter belt) L. H.	1922-23	60
10042BX	Rail (rear quarter belt) R. H.	1922-23	75
10043BX	Rail (rear quarter belt) L. H.	1922-23	75
10054X	Rail (rear belt) assy.	1915-23	3 25
10199X	Rail (rear quarter belt) and pillar face assy.—R. H.	1915-21	4 00
10200X	Rail (rear quarter belt) and pillar face assy.—L. H.	1915-21	4 00
10026BX	Rail (roof) front	1922-23	2 00
10026AX	Rail (roof) front—specify make of body	1915-21	3 50
10142X	Rail (roof) rear assy.	1922-23	3 00
10024X	Rail (roof) rear—specify make of body	1915-21	7 00
10021AX	Rail (roof) side—R. H.—specify make of body	1915-21	7 00
10021BX	Rail (roof) side—R. H.	1922-23	3 50
10022AX	Rail (roof) side—L. H.—specify make of body	1915-21	7 00
10022BX	Rail (roof) side—L. H.	1922-23	3 50
10104X	Rest (door lock pillar sash)	1922-23	05
10105X	Rest (door sash)	1915-21	05
10092X	Rest (front quarter sash)	1915-21	15
10151X	Rest (front quarter sash) R. H.	1922-23	30
10152X	Rest (front quarter sash) L. H.	1922-23	30
10153X	Rest (rear quarter sash) R. H.	1915-23	40
10154X	Rest (rear quarter sash) L. H.	1915-23	40
5092X	Retainer (door window weather strip)	1922-23	15
9879X	Retainer (driver's seat cushion)	1915-23	40
5096X	Retainer (front quarter window weather strip)	1922-23	15
5399X	Retainer (instrument panel)	1922-23	20
9264X	Retainer (rear seat cushion)	1915-23	40
10085X	Rib (roof) center	1915-23	50
10083X	Rib (roof) front	1915-23	50
10087X	Rib (roof) rear	1915-23	50
10156X	Riser (front floor board) assy.—R. H.	1915-23	1 00
10157X	Riser (front floor board) assy.—L. H.	1915-23	1 00
10094X	Riser (rear seat front)	1915-21	1 00

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.



Part No.	NAME	YEAR	PRICE	Tax Status
SEDAN BODY PARTS—Continued				
5076X	Strip (rear quarter pillar finish)	1922	\$ 0	30
9296X	Strip (roof moulding finish)	1922-23	25	
9520AX	Support (driver's and pass. seat back) R. H.	1916-22	50	
9521X	Support (driver's and pass. seat back) L. H.	1916-22	50	
9520BX	Support (driver's and pass seat back)—pressed steel design	1921-23	25	
10247ARX	Trimming (body hinge pillar) assembly	1922-23	30	
10247BX	Trimming (body hinge pillar) assembly	1923	30	
10250ARX	Trimming (body lock pillar) assembly	1922-23	30	
10250BX	Trimming (body lock pillar) assembly	1923	30	
10241ARX	Trimming (coupe pillar) assembly—R. H.	1922-23	30	
10241BX	Trimming (coupe pillar) assembly—R. H.	1923	30	
10242ARX	Trimming (coupe pillar) assembly—L. H.	1922-23	30	
10242BX	Trimming (coupe pillar) assembly—L. H.	1923	30	
10244ARX	Trimming (door header) assembly	1922-23	30	
10244BX	Trimming (door header) assembly	1923	30	
10248ARX	Trimming (door hinge pillar) assembly	1922-23	30	
10248BX	Trimming (door hinge pillar) assembly	1923	30	
10249ARX	Trimming (door lock pillar) assembly	1922-23	30	
10249BX	Trimming (door lock pillar) assembly	1923	30	
10245ARX	Trimming (door weather strip) assembly	1922-23	30	
10245BX	Trimming (door weather strip) assembly	1923	30	
10243ARX	Trimming (front quarter header) assy.	1922-23	30	
10243BX	Trimming (front quarter header) assy.	1923	30	
10246ARX	Trimming (rear quarter header) assembly	1922-23	30	
10246BX	Trimming (rear quarter header) assembly	1923	30	
9752X	Upholstering (cowl) upper	1915-19	2 00	
9684ARX	Upholstering (door) assy.—R. H.—specify year	1917-21	1 50	
9684BX	Upholstering (door) assy.—R. H.	1922-23	4 50	
9684CX	Upholstering (door) assy.—R. H.	1923	4 50	
9685ARX	Upholstering (door) assy.—L. H.—specify year	1917-21	1 50	
9685BX	Upholstering (door) assy.—L. H.	1922-23	4 50	
9685CX	Upholstering (door) assy.—L. H.	1923	4 50	
10454X	Upholstering (driver's and pass seat back) assy.—front	1921	1 10	
10455X	Upholstering (driver's and pass. seat back)—rear	1921	1 10	
10353AX	Upholstering (driver's seat back) assy.—front—malleable design	1922	3 50	
10353BX	Upholstering (driver's seat back) assy.—front—pressed steel design	1922	3 50	
10353CX	Upholstering (driver's seat back) assy.—front—pressed steel design	1923	3 50	
10354AX	Upholstering (driver's seat back) assy.—rear—malleable design	1922	1 75	
10354BX	Upholstering (driver's seat back) assy.—rear—pressed steel design	1922	1 75	
10354CX	Upholstering (driver's seat back) assy.—rear—pressed steel design	1923	1 75	
10453AX	Upholstering (driver's seat cushion) assy.	1917-21	2 00	
10453BX	Upholstering (driver's seat cushion) assy.	1922-23	4 50	
10453CX	Upholstering (driver's seat cushion) assy.	1923	4 50	
9698AX	Upholstering (front quarter) R. H.—specify year	1915-21	1 75	
9699X	Upholstering (front quarter) L. H.—specify year	1915-21	1 75	
9698BX	Upholstering (front quarter) assy.	1922-23	4 00	
9698CX	Upholstering (front quarter) assy.	1923	4 00	
10274BX	Upholstering (pass. seat back) assy.—front—malleable design	1922	2 75	
10274CX	Upholstering (pass. seat back) assy.—front—pressed steel design	1922	2 75	
10274DX	Upholstering (pass. seat back) assy.—front—pressed steel design	1923	2 75	
10458BX	Upholstering (pass. seat back) assy.—rear—malleable design	1922	2 50	
10455CX	Upholstering (pass. seat back) assy.—rear—pressed steel design	1922-23	2 50	
10455DX	Upholstering (pass. seat back) assy.—rear—pressed steel design	1923	2 50	
10456BX	Upholstering (pass. seat cushion) assy.	1916-22	2 00	
10456CX	Upholstering (pass. seat cushion) assy.	1922-23	4 00	
10456DX	Upholstering (pass. seat cushion) assy.	1923	4 00	
10349AX	Upholstering (rear quarter) assy.—R. H.—specify year	1915-21	1 75	
10349BX	Upholstering (rear quarter) assy.—R. H.	1922-23	3 00	
10349CX	Upholstering (rear quarter) assy.—R. H.	1923	3 00	
10350AX	Upholstering (rear quarter) assy.—L. H.—specify year	1915-21	1 75	
10350BX	Upholstering (rear quarter) assy.—L. H.	1922-23	3 00	
10350CX	Upholstering (rear quarter) assy.—L. H.	1923	3 00	
9683X	Upholstering (rear seat back) assy.	1918-19	16 00	
10451AX	Upholstering (rear seat back) assy.	1920-21	6 50	


Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

Part No.	NAME	YEAR	PRICE	Tax Status
SEDAN BODY PARTS—Continued				
10451BX	Upholstering (rear seat back) assy.	1922-23	\$ 7	50
10451CX	Upholstering (rear seat back) assy.	1923	7 50	
10450AX	Upholstering (rear seat cushion) assy.—specify year	1915-21	6 00	
10450BX	Upholstering (rear seat cushion) assy.	1922-23	9 00	
10450CX	Upholstering (rear seat cushion) assy.	1923	9 00	
9668BX	Washer (window lifter rod)	1922-23	01	
9661AX	Window (door) R. H.	1915-20	8 00	M H
9661BX	Window (door) R. H.	1921	8 00	M H
9662AX	Window (door) L. H.	1915-20	8 00	M H
9662BX	Window (door) L. H.	1921	8 00	M H
9596X	Window (front quarter) R. H.	1915-21	8 25	M H
9597X	Window (front quarter) L. H.	1915-21	8 25	M H
9602X	Window (rear quarter) R. H.	1915-21	8 75	M H
9603X	Window (rear quarter) L. H.	1915-21	8 75	M H
†Window lifter not included.				

#### FOUR-DOOR SEDAN BODY PARTS

8320B	Anti-rattler (door lock lever)	1923	05	
18802X	Anti-rattler (window regulator handle)	1923	01	
5052ARX	Anti-rattler (door) assy.—female	1923	30	
5053ARX	Anti-rattler (door) assy.—male	1923	15	
17316X	Arm (windshield swing)	1923	1 00	
5104X	Arm (window lifter counterbalance) assy. R. H.	1923	40	
5103X	Arm (window lifter counterbalance) assy. L. H.	1923	40	
17141X	Back (front seat) assy.—less trimming	1923	10 00	
18041X	Back (rear seat) assy.—complete	1923	25 00	
18210X	Beading (roof) front	1923	45	
18211X	Beading (roof) rear	1923	50	
16014X	Board (dome light)	1923	60	
16023X	Board (instrument)	1923	1 00	
16020X	Board (floor) No. 4	1923	50	M H
16021X	Board (floor) No. 5 and 6	1923	60	M H
16022X	Board (floor) No. 7	1923	70	M H
16131X	Board (rear door garnish) R. H.	1923	50	
16132X	Board (rear door garnish) L. H.	1923	50	
16132X	Board (front door garnish) R. H.	1923	50	
16131X	Board (front door garnish) L. H.	1923	50	
16133X	Board (rear door lock) R. H.	1923	75	
16134X	Board (rear door lock) L. H.	1923	75	
16134X	Board (front door lock) R. H.	1923	75	
16133X	Board (front door lock) L. H.	1923	75	
16135X	Board (front door bottom) and bar assy. R. H.	1923	1 00	
16136X	Board (front door bottom) and bar assy. L. H.	1923	1 00	
16154X	Board (rear door bottom) bar and block assy. R. H.	1923	1 50	
16155X	Board (rear door bottom) bar and block assy. L. H.	1923	1 50	
9495X	Board (floor) No. 1 and plate assy.	1923	1 00	M H
9496X	Board (floor) No. 2 and plate assy.	1923	1 00	M H
8169X	Board (floor) No. 3 and plate assy.	1923	1 70	M H
17335X	Bolt (windshield swing arm brkt.)	1923	15	
17068X	Brace (roof rib No. 4) R. H.	1923	10	
17069X	Brace (roof rib No. 4) L. H.	1923	10	
17050X	Brace (coupe pillar) R. H.	1923	30	
17051X	Brace (coupe pillar) L. H.	1923	30	
17052X	Brace (body lock pillar)	1923	25	
17054BX	Brace (body hinge pillar) R. H.	1923	60	
17054ARX	Brace (body hinge pillar) R. H.	1923	60	
17055BX	Brace (body hinge pillar) L. H.	1923	60	
17055ARX	Brace (body hinge pillar) L. H.	1923	60	
17056BX	Brace (quarter pillar) R. H.	1923	80	
17056ARX	Brace (quarter pillar) R. H.	1923	80	
17057BX	Brace (quarter pillar) L. H.	1923	80	
17057ARX	Brace (quarter pillar) L. H.	1923	80	
17058X	Brace (body lock pillar to roof rail) R. H.	1923	15	
17059X	Brace (body lock pillar to roof rail) L. H.	1923	15	
17060RX	Bracket (rear fender attachment) R. H.	1923	45	
17061RX	Bracket (rear fender attachment) L. H.	1923	45	
17063X	Bracket (body) rear	1923	30	
17066RX	Bracket (quarter pillar brace to riser)	1923	10	
17066X	Bracket (visor)	1923	10	
17312X	Bracket (windshield swing arm) on channel	1923	20	
17317X	Bracket (windshield swing arm) on frame	1923	15	
17042X	Bracket (ventilator hinge) on cowl	1923	20	
17043X	Bracket (ventilator hinge) on shield	1923	10	
6927B1X	Bumper (door) short	1923	05	
18903RX	Bulb (dome light)	1923	30	
6520X	Bulb (dome light)	1923	20	
17352X	Cap (visor bracket to visor rivet)	1923	05	dz.
18120X	Carpet (floor) front assy.	1923	4 50	M H

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.




Note:—Where marked R. H. there is always a left hand of the same piece or vice versa.

Part No.	NAME	YEAR	Tax PRICE Status
<b>FOUR-DOOR SEDAN BODY PARTS—Continued</b>			
18121ARX	Carpet (floor) rear assy.—19 1/4" long	1923	\$ 4 50 M H
18121BX	Carpet (floor) rear assy.—17 1/4" long	1923	4 50 M H
18122ARX	Carpet (front seat heel board) assy.—41 1/4" long	1923	2 25
18122BX	Carpet (front seat heel board) assy.—38 1/2" long	1923	2 25
18124X	Carpet (cowl) assy.—R. H.	1923	80
18125X	Carpet (cowl) assy.—L. H.	1923	80
18126ARX	Carpet (rear seat riser) assy.—6 1/8" wide	1923	1 25
18126CX	Carpet (rear seat riser) assy.—54 1/2" long	1923	1 25
18126BRX	Carpet (rear seat riser) assy.—5 1/2" wide	1923	1 25
18127RX	Carpet (front door) assy.	1923	75
18128RX	Carpet (rear door) assy.—R. H.	1923	75
18129RX	Carpet (rear door) assy.—L. H.	1923	75
18130RX	Carpet (front rocker) assy.—R. H.	1923	40
18131RX	Carpet (front rocker) assy.—L. H.	1923	40
18132RX	Carpet (rear rocker) assy.—R. H.	1923	40
18133RX	Carpet (rear rocker) assy.—L. H.	1923	40
18123ARX	Carpet (rear seat toe board) assy.	1923	1 75
18116X	Carpet (rear seat toe board) assy.—end—R. H.	1923	40
18117X	Carpet (rear seat toe board) assy.—end—L. H.	1923	40
18118X	Carpet (rear seat toe board) assy.—center	1923	1 25
18140X	Cardboard (door weather strip) assy.	1923	40
18141X	Cardboard (door header breakover) assy.	1923	20
18142X	Cardboard (door hinge pillar breakover) assy.	1923	20
18143X	Cardboard (door lock pillar breakover) assy.	1923	20
18145X	Cardboard (body hinge pillar breakover) assy.—R. H.	1923	20
18146X	Cardboard (body hinge pillar breakover) assy.—L. H.	1923	20
18147X	Cardboard (body lock pillar breakover) assy.—lower	1923	20
18144X	Cardboard (body lock pillar breakover) assy.—upper	1923	40
18148X	Cardboard (coupe pillar breakover) assy.—R. H.	1923	30
18149X	Cardboard (coupe pillar breakover) assy.—L. H.	1923	30
18139X	Cardboard (front seat back frame side breakover) assy.	1923	40
9101BX	Casing (door bumper)	1923	15
17118X	Channel (door window glass) assy.	1923	35
17121X	Channel (quarter window glass) R. H.	1923	35
17122X	Channel (quarter window glass) L. H.	1923	35
18821AX	Channel (back window glass) side (used with thin glass)	1923	10
18821BX	Channel (back window glass) side (used with thick glass)	1923	10
18804AX	Channel (back window glass) upper and lower (used with thin glass)	1923	10
18804BX	Channel (back window glass) upper and lower (used with thick glass)	1923	10
18800X	Channel (windshield center)	1923	60
17331X	Clip (windshield glass)—lower	1923	10
17322X	Clip (windshield glass)—upper R. H.	1923	05
17323X	Clip (windshield glass)—upper L. H.	1923	05
17325X	Clip (windshield finger)	1923	10
18050X	Cloth (trimming) striped	1923	5 00 yd
18053X	Cloth (front seat back trimming)—rear	1923	2 50
18076X	Cloth (trimming) plain	1923	4 00 yd
18073X	Cloth (quarter header trimming)	1923	20
18213X	Cord (seaming) assy.—headlining cloth	1923	10 yd
18182X	Cord (covered seaming)	1923	10 yd
18212X	Cord (seaming) assy.—body cloth	1923	15 yd
17048X	Cover (ventilator) assy.	1923	65
10366A1X	Curtain (back window) assy.	1923	3 00
10300A1X	Curtain (quarter window) assy.	1923	2 50
18190X	Cushion (rear seat) assy.	1923	*15 00
18191X	Cushion (rear seat back) assy.	1923	15 00
18192X	Cushion (front seat) assy.—R. H.	1923	10 00
18193X	Cushion (front seat) assy.—L. H.	1923	10 00
2069X	Cushion (steering column)	1923	05
9462X	Cushion (window)	1923	05
5057X	Cushion (door anti-rattler)	1923	75
18902AX	Dome (dome light) assy.	1923	05
18902BX	Dome (dome light) assy.	1923	75
16112X	Door (battery trap) assy.	1923	1 50
18035X	Door (front) assy.—R. H.—complete	1923	*45 00
18036X	Door (front) assy.—L. H.—complete	1923	*45 00
18037X	Door (rear) assy.—R. H.—complete	1923	*45 00
18038X	Door (rear) assy.—L. H.—complete	1923	*45 00
17065X	Dowel (rear seat cushion)	1923	05
17076X	Dowel (front seat cushion)	1923	05
16019X	Frame (back window) assy.	1923	1 50
16100X	Frame (roof) assy.	1923	*20 00
16138X	Frame (front seat back) upper assy.	1923	3 50
16142X	Frame (front seat back) lower assy.	1923	2 25
10155X	Frame (cowl) assy.	1923	2 00

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.






Note:—Where marked R. H. there is always a left hand of the same piece or vice versa

Part No.	NAME	YEAR	Tax PRICE STATUS
----------	------	------	------------------

#### FOUR-DOOR SEDAN BODY PARTS—Continued

17300X	Frame (windshield—upper top hinge and channel assy.)	1923	\$ 5 00
18830X	Glass (back window)	1923	
18831X	Glass (quarter window)	1923	
18833X	Glass (front door window)	1923	
18832X	Glass (rear door window)	1923	
18834X	Glass (windshield) lower	1923	
18835X	Glass (windshield) upper	1923	
18854X	Glass (front door, window and channel) assy.—R. H.	1923	
18855X	Glass (front door window and channel) assy.—L. H.	1923	
18856X	Glass (rear door, window and channel) assy.	1923	
18857X	Glass (quarter window channel) assy.—R. H.	1923	
18858X	Glass (quarter window channel) assy.—L. H.	1923	
17130X	Grip (door lock) and ferrule assy.	1923	1 25
17221X	Handle (window regulator) assy.	1923	80
17273X	Handle (door lock—dog shaft)	1923	20
17044X	Handle (ventilator)	1923	10
16090X	Header (windshield)	1923	1 25
16091X	Header (front door) R. H.	1923	70
16092X	Header (front door) L. H.	1923	70
16093X	Header (rear door) R. H.	1923	70
16094X	Header (rear door) L. H.	1923	70
16095X	Header (quarter) R. H.	1923	60
16096X	Header (quarter) L. H.	1923	60
17172X	Hinge (rear door) upper assy.—L. H.	1923	65
17172X	Hinge (front door) assy.—R. H.	1923	65
17175X	Hinge (rear door) center assy.—L. H.	1923	65
17175X	Hinge (front door) center assy.—R. H.	1923	65
17178X	Hinge (rear door) lower assy.—L. H.	1923	65
17178X	Hinge (front door) lower assy.—R. H.	1923	65
17180X	Hinge (front door) upper assy.—L. H.	1923	65
17180X	Hinge (rear door) upper assy.—R. H.	1923	65
17186X	Hinge (rear door) assy.—lower R. H.	1923	65
17186X	Hinge (front door) assy.—lower L. H.	1923	65
17183X	Hinge (front door) assy.—center L. H.	1923	65
17183X	Hinge (rear door) assy.—center R. H.	1923	65
17090X	Housing (rear cross member) assy.	1923	1 50
17282X	Key (Yale lock) (specify serial number)	1923	15
17261ARX	Knob (door lock lever)	1923	15
17261BX	Knob (door lock lever)	1923	15
18214X	Lace (wind) assy.	1923	25 yd
18160X	Leather (roof)	1923	9 00
18913X	Lens (dome light)	1923	10
18044X	Lining (head) assy.	1923	8 00
17279X	Lock (Yale) and keys	1923	1 50
17250X	Lock (rear door) assy.—R. H.	1923	1 75
17251X	Lock (rear door) assy.—L. H.	1923	1 75
17252X	Lock (front door) assy.—R. H.	1923	1 75
17250X	Lock (front door) assy.—L. H.	1923	1 75
17123X	Moulding (roof drip)	1923	55
17150X	Moulding (front door lock pillar "T") R. H.	1923	70
17151X	Moulding (front door lock pillar "T") L. H.	1923	70
17151X	Moulding (rear door lock pillar "T") R. H.	1923	70
17150X	Moulding (rear door lock pillar "T") L. H.	1923	70
17152X	Moulding (front door bottom "T")	1923	45
17153X	Moulding (front door hinge pillar "T") lower R. H.	1923	20
17154X	Moulding (front door hinge pillar "T") lower L. H.	1923	20
17155X	Moulding (front door hinge pillar "T") center lower	1923	35
17156X	Moulding (front door hinge pillar "T") center upper	1923	25
17157X	Moulding (front door hinge pillar "T") upper	1923	15
17158X	Moulding (rear door bottom "T") R. H.	1923	55
17159X	Moulding (rear door bottom "T") L. H.	1923	55
17155X	Moulding (rear door hinge pillar "T") center—lower	1923	35
17160X	Moulding (rear door hinge pillar "T") center—upper	1923	25
17157X	Moulding (rear door hinge pillar "T") upper	1923	15
17162X	Moulding (front belt)	1923	1 25
17164X	Moulding (rear belt)	1923	80
17164X	Moulding (back panel) upper R. H.	1923	30
17165X	Moulding (back panel) upper L. H.	1923	30
17166X	Moulding (back panel) lower	1923	40
17167X	Moulding (quarter belt) R. H.	1923	1 25
17168X	Moulding (quarter belt) L. H.	1923	1 25
18218X	Moulding (front seat) assy.—side	1923	20
18216X	Moulding (front seat) assy.—back	1923	50
17334X	Nut (windshield swing arm bracket bolt)	1923	15
5085BX	Nut (window lifter support rod)	1923	08
17001X	Panel (front door) R. H.	1923	9 00
17002X	Panel (front door) L. H.	1923	9 00

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.



Note: Where marked R. H. there is always a left hand of the same piece or vice versa

Part No.	NAME	YEAR	PRICE	Tax Status
----------	------	------	-------	------------

#### FOUR-DOOR SEDAN BODY PARTS—Continued

17003X	Panel (rear door) R. H.	1923	\$ 9 00	
17004X	Panel (rear door) L. H.	1923	9 00	
17005X	Panel (quarter) upper R. H.	1923	5 00	
17006X	Panel (quarter) upper L. H.	1923	5 00	
17007X	Panel (quarter) lower R. H.	1923	10 00	
17008X	Panel (quarter) lower L. H.	1923	10 00	
17009X	Panel (front rocker) R. H.	1923	75	
17010X	Panel (front rocker) L. H.	1923	75	
17011X	Panel (rear rocker) R. H.	1923	75	
17012X	Panel (rear rocker) L. H.	1923	75	
17016X	Panel (instrument)	1923	1 50	
17017X	Panel (front belt rail)	1923	1 10	
17018X	Panel (front roof rail)	1923	1 10	
17027X	Panel (coupe pillar) R. H.	1923	1 00	
17028X	Panel (coupe pillar) L. H.	1923	1 00	
17021X	Panel (front seat back panel)	1923	2 00	
17022X	Panel (windshield header)	1923	75	
17023X	Panel (back) upper	1923	15 00	
17024X	Panel (back) lower	1923	10 00	
17025X	Panel (body lock pillar) R. H.	1923	1 25	
17026X	Panel (body lock pillar) L. H.	1923	1 25	
17029X	Panel (quarter corner) R. H.	1923	15	
17030X	Panel (quarter corner) L. H.	1923	15	
17019X	Panel (owl) Assy.	1923	15 00	
16050X	Pillar (coupe) R. H.	1923	4 00	
16051X	Pillar (coupe) L. H.	1923	4 00	
16054X	Pillar (body hinge) Assy.—R. H.	1923	4 00	
16055X	Pillar (body hinge) Assy.—L. H.	1923	4 00	
16056X	Pillar (quarter) R. H.	1923	1 25	
16057X	Pillar (quarter) L. H.	1923	1 25	
16058X	Pillar (front door hinge) R. H.	1923	2 00	
16059X	Pillar (front door hinge) L. H.	1923	2 00	
16060X	Pillar (front door lock) R. H.	1923	3 00	
16061X	Pillar (front door lock) L. H.	1923	3 00	
16062X	Pillar (rear door lock) R. H.	1923	3 00	
16063X	Pillar (rear door lock) L. H.	1923	3 00	
16064X	Pillar (rear door hinge) R. H.	1923	2 00	
16065X	Pillar (rear door hinge) L. H.	1923	2 00	
17142X	Pillar (body lock) Assy.—R. H.	1923	4 00	
17143X	Pillar (body lock) Assy.—L. H.	1923	4 00	
17047X	Pin (ventilator hinge clevis)	1923	01	
17113X	Plate (front door scuff) R. H.	1923	25	
17114X	Plate (front door scuff) L. H.	1923	25	
17115X	Plate (rear door scuff) R. H.	1923	25	
17116X	Plate (rear door scuff) L. H.	1923	25	
17227X	Plate (window regulator escutcheon)	1923	15	
17276X	Plate (door lock striker)	1923	15	
17129RX	Plate (steering column)	1923	10	
17274X	Plate (door lock dog shaft escutcheon)	1923	05	
17045X	Quadrant (ventilator handle)	1923	95	
17111X	Rack (quarter window lifter) R. H.	1923	50	
17112X	Rack (quarter window lifter) L. H.	1923	50	
16070X	Rail (front belt)	1923	75	
16071X	Rail (front door belt) R. H.	1923	45	
16072X	Rail (front door belt) L. H.	1923	45	
16073X	Rail (rear door belt) R. H.	1923	45	
16074X	Rail (rear door belt) L. H.	1923	45	
16075X	Rail (quarter belt) R. H.	1923	1 25	
16076X	Rail (quarter belt) L. H.	1923	1 25	
16077X	Rail (rear belt) Assy.	1923	3 00	
16081X	Rail (roof) side—R. H.	1923	4 00	
16082X	Rail (roof) side—L. H.	1923	4 00	
16083X	Rail (roof) rear Assy.	1923	4 50	
16087X	Rail (roof) front	1923	2 00	
18901BX	Reflector (dome light) Assy.	1923	75	
17200X	Regulator (window) Assy.—rear door—R. H.	1923	3 00	
17201X	Regulator (window) Assy.—rear door—L. H.	1923	3 00	
17201X	Regulator (window) Assy.—front door—R. H.	1923	3 00	
17200X	Regulator (window) Assy.—front door—L. H.	1923	3 00	
16041X	Rest (quarter sash) R. H.	1923	35	
16042X	Rest (quarter sash) L. H.	1923	35	
16043X	Rest (rear door lock pillar sash)	1923	05	
16045X	Rest (front door sash)	1923	05	
16097X	Rest (quarter sash) Assy.—R. H.	1923	40	
16098X	Rest (quarter sash) Assy.—L. H.	1923	40	
17315X	Retainer (windshield glass) upper	1923	40	
17314X	Retainer (windshield glass) lower	1923	40	
16120X	Rib (roof) No. 1	1923	50	
16121X	Rib (roof) No. 2	1923	50	
16122X	Rib (roof) No. 3	1923	50	

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

Part No.	NAME	YEAR	PRICE	Tax Status
----------	------	------	-------	------------

FOUR-DOOR SEDAN BODY PARTS—Continued

16123X	Rib (roof) No. 4	1923	\$ 0 50	
16124X	Rib (roof) No. 5	1923	50	
16026X	Riser (rear seat) front	1923	1 00	
16027X	Riser (rear seat) rear	1923	75	
16032X	Riser (floor board) assy.—R. H.	1923	90	
16033X	Riser (floor board) assy.—L. H.	1923	90	
17351X	Rivet (visor bracket to visor)	1923	01	
17145X	Rod (window lifter support) and nut assy.—L. H.	1923	60	
17146X	Rod (window lifter support) and nut assy.—R. H.	1923	60	
9759A1X	Roller (back window curtain) assy.	1923	1 25	
9758A1X	Roller (quarter window curtain) assy.	1923	1 25	
18810X	Runs (door window glass)	1923	75	
18811X	Runs (quarter window glass)	1923	75	
17277X	Screw (door lock dog shaft handle)	1923	01	
17225X	Screw (window regulator handle)	1923	10	
17283X	Set screw (Yale lock)	1923	05	
17320RX	Screw (windshield swing arm) bracket	1923	10	
17330X	Screw (windshield swing arm thumb)	1923	40	
17272AX	Shaft (door lock—dog) (Ford design)	1923	25	
17272BX	Shaft (door lock—dog) (Ferro design)	1923	25	
16603X	Sill (cross) front	1923	45	
16604X	Sill (cross) center	1923	85	
16605X	Sill (cross) rear	1923	1 25	
16606X	Sill (side) and rocker assy.—R. H.	1923	5 50	
16607X	Sill (side) and rocker assy.—L. H.	1923	5 50	
16125X	Slat (roof frame)	1923	25	
56670X	Spring (window lifter support rod)	1923	03	
5092X	Spring (window lifter counterbalance)	1923	15	
18220X	Spring (front seat cushion) assy.—R. H.	1923	1 35	
18221X	Spring (front seat cushion) assy.—L. H.	1923	1 35	
18222X	Spring (front seat back) assy.	1923	1 25	
18223X	Spring (rear seat cushion) assy.	1923	3 25	
9938X	Spring (rear seat back) assy.	1923	2 00	
16043X	Strainer (back panel) upper	1923	30	
16046X	Strainer (back panel) lower R. H.	1923	75	
16047X	Strainer (back panel) lower L. H.	1923	75	
16048X	Strainer (back panel) lower center	1923	1 00	
17102X	Strip (header finish)	1923	25	
17103X	Strip (quarter garnish finish) R. H.	1923	30	
17104X	Strip (quarter garnish finish) L. H.	1923	30	
17106X	Strip (front door garnish finish) R. H.	1923	20	
17105X	Strip (front door garnish finish) L. H.	1923	20	
17105X	Strip (rear door garnish finish) R. H.	1923	20	
17106X	Strip (rear door garnish finish) L. H.	1923	20	
17107X	Strip (rear door pillar finish)	1923	20	
17108X	Strip (front door hinge pillar finish)	1923	20	
17107X	Strip (front door lock pillar finish)	1923	20	
17110X	Strip (quarter pillar finish)	1923	20	
17111X	Strip (back window finish) assy.	1923	1 25	
17125X	Strip (roof drip moulding finish)	1923	25	
10239AX	Strip (window glass retaining) thick	1923	15	
10239BX	Strip (window glass retaining) thin	1923	15	
18801X	Strip (window header weather)	1923	20	
18803X	Strip (door window weather)	1923	10	
18850X	Strip (window weather) and retainer assy.	1923	25	
17074X	Support (instrument board) and cowl brace assy.—R. H.	1923	65	
17075X	Support (instrument board) and cowl brace assy.—L. H.	1923	65	
18904AX	Switch (dome light)	1923	75	
18904BX	Switch (dome light) assy.	1923	35	
*18020ARX	Upholstering (front door) assy.—R. H.	1923	3 50	
18020BX	Upholstering (front door) assy.—R. H.	1923	2 75	
*18021ARX	Upholstering (front door) assy.—L. H.	1923	3 50	
18021BX	Upholstering (front door) assy.—L. H.	1923	2 75	
*18029ARX	Upholstering (rear door) assy.—R. H.	1923	3 50	
18029BX	Upholstering (rear door) assy.—R. H.	1923	2 75	
*18030X	Upholstering (rear door) assy.—L. H.	1923	3 50	
18030BX	Upholstering (rear door) assy.—L. H.	1923	2 75	
18022X	Upholstering (quarter) assy.—R. H.	1923	2 25	
18023X	Upholstering (quarter) assy.—L. H.	1923	2 25	
18024X	Upholstering (front seat cushion) assy.—R. H.	1923	4 50	
18025X	Upholstering (front seat cushion) assy.—L. H.	1923	4 50	
18026X	Upholstering (front seat back) assy.	1923	8 00	
18027X	Upholstering (rear seat cushion) assy.	1923	8 00	
18028X	Upholstering (rear seat back cushion) assy.	1923	8 00	
18150X	Visor and bracket assy.	1923	3 75 M H	
17226X	Washer (window regulator handle screw lock)	1923	02	
17224X	Washer (window regulator handle anti-rattler)	1923	01	

\*With carpet at bottom.

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

Part No.	NAME	YEAR	PRICE	Tax Status
----------	------	------	-------	------------

FOUR-DOOR SEDAN BODY PARTS—Continued

17350X	Washer (visor to roof rail screw finishing)	1923	\$ 0 01	
17313BX	Washer (windshield swing arm bracket screw)	1923	03	
17313ARX	Washer (windshield swing arm bracket screw)	1923	03	
18861X	Windshield assy.—upper half	1923		
18852X	Windshield assy.—lower half	1923		
18853X	Windshield assy.—complete	1923		
18911X	Wire (dome light switch to light) assy.	1923	25 M H	
18907RX	Wire (dome light switch to ammeter) assy.	1923	40 M H	
18909RX	Wire (dome light to ground) assy.	1923	25 M H	
18917X	Wire (dome light to ammeter) assy.	1923	30 M H	
18919X	Wire (dome light switch to ground) assy.	1923	15 M H	

Of the net amount at which these parts are billed to purchasers who purchase direct from the Ford Motor Company (except parts which show no Tax Status, if any) 20/21 represents the price of the goods and 1/21 represents excise tax.

